





report date: 2024-03-28

### General information

Make	HYUNDAI
Model	I30 CRDI SE BLUE DRIVE
Colour	Grey
Year of manufacture	2015
Top speed	117 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 2

Date	2021-06-12
Pictures	23

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

Date	2021-06-06
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



YN65ZGT report date: 2024-03-28

MOT history
-------------

MOT expiry date	2024-06-25
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #8	2023-06-17 08:52
MOT test number	748367152171
Result	✓ Passed
Next expiry date	2024-06-25
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #7	2022-06-11 11:58
MOT test number	915919841407
Result	✓ Passed
MOT #6	2021-06-26 07:59
MOT test number	113861619718
Result	✓ Passed
MOT #5	2021-06-25 16:22
MOT test number	323287809169
Result	<b>X</b> Failed
Fail Front Windscreen washer not working (3.5 (a))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice
Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice
Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice
Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice
Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT** #3 2020-09-25 07:37 **MOT** test number 896931445564 Result × Failed **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Pass with rectification Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) **Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

MOT test number

Result

Advice Very slight splitting of front inner wish bone bushes no movement

2019-09-26 09:26

321310688783

✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1		2018-09-27 07:42
MOT test	number	876851851111
Result		✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	25 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK JK
Plate since	
	Moro info

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-30
Last registration	2023-06-17
Complete history	See info



Registration #1	2015-09-30	12 mi
Registration #2	2018-09-27	35.774 mi
Registration #3	2019-09-26	45.863 mi
Registration #4	2020-09-25	55.173 mi
Registration #5	2020-09-25	55.173 mi
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		0.00 44
Registration #11		10.777 esc

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1429 kg
Max. allowed weight	1920 kg

## Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/:

Number of axles 2

**Engine number** D4FBFZ007917