



SMI4WWH


report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA TECH LINE
Colour	Black
Year of manufacture	2014
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





MOT history

MOT expiry date	2024-09-07
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #9	2023-09-08 12:11
MOT test number	915935822776
Result	✓ Passed
Next expiry date	2024-09-07
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2023-09-08 11:11
MOT test number	941711709085
Result	✗ Failed
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7** 2022-09-08 12:08**MOT test number** 203679933778**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2021-07-24 10:21**MOT test number** 267729947520**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #5** 2020-08-03 07:58**MOT test number** 835385859460**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #4** 2019-07-08 08:00**MOT test number** 463486391482**Result** ✓ Passed**MOT #3** 2018-07-16 09:17**MOT test number** 924608165751**Result** ✓ Passed**MOT #2** 2017-08-17 08:49**MOT test number** 775799633325**Result** ✓ Passed



MOT #1	2017-04-24 15:16
MOT test number	747120112285
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
7 September 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 SM14WWH
Plate since	2019-03-29
Current registration	 SM14WWH
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-08-13
Last registration	2023-09-08
Complete history	See info



Registration #1	2014-08-13	26 mi
Registration #2	2017-04-24	18.645 mi
Registration #3	2017-08-17	18.701 mi
Registration #4	2018-07-16	28.129 mi
Registration #5	2019-07-08	37.652 mi
Registration #6	2020-06-29	46.277 mi
Registration #7	2021-06-29	55.277 mi
Registration #8	2022-06-29	64.277 mi
Registration #9	2023-06-29	73.277 mi
Registration #10	2023-09-08	74.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19EF8057LDD