





report date: 2024-03-29

### General information

Make	VOLVO
Model	S60 D3 BUSINESS EDITION
Colour	Blue
Year of manufacture	2016
Top speed	134 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В



CarCheck.co.uk page 1/11



**KW16YKG** 

report date: 2024-03-29

## Internet history


### Entry 1


Date 2022-02-18

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-09
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	4
Total items failed	3

MOT #7	2024-01-10 11:38
MOT test number	893617627081
Result	✓ Passed
Next expiry date	2025-01-09

MOT #6	2022-11-18 14:31
MOT test number	753889593908
Result	✓ Passed
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2022-11-18 10:26
MOT test number	749604942395
Result	🗙 Failed
Fail Rear Registration plate does not conform to the specified requirements (0.1 (d))	
Fail Front Registration plate does not conform to the specified requirements (0.1 (d))	
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2021-11-17 13:42
MOT test number	408630112508
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3 2021-11-16 13:33

MOT test number 216281603108

Result

× Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2 2020-12-07 14:24

MOT test number 828987671390

Result 

Passed

Advice

Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #1** 2019-05-14 11:02

MOT test number 303229795765

**Result** ✓ Passed

Advice Tyre worn close to legal limit/worn on edge both front tyres 235/40/r18 95 w contisport contract 3 (2.5mm) (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	9 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



**KW16YKG** 

report date: 2024-03-29

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
********	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	IIK SIE
Plate since	
Current registration	OK ON THE OWNER OF THE OWNER OW
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



**KW16YKG** 

report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-01
Last registration	2024-01-10
Complete history	See info



Registration #1	2016-06-01	17 mi
Registration #2	2019-05-14	24.659 mi
Registration #3	2020-12-07	27.931 mi
Registration #4	2021-11-16	29.323 mi
Registration #5	2021-11-17	29.325 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.377 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1580 kg
Max. allowed weight	2090 kg

### Additional information

Fuel tank capacity	67 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 1798437