





### General information

Make	VOLVO
Model	XC60 D4 SE NAV
Colour	Grey
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	188 BHP	
Max. torque	400 Nm at 1.750 rpm	
Engine capacity	1.969 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	57.7 mpg	
Consumption extra urban	67.3 mpg	
Consumption combined	62.8 mpg	
CO2 emission	117 g/km	
CO2 label	С	





Internet history	
Entry 1	
Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



### MOT history

MOT expiry date	2025-02-20
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	13
Total items failed	1

МОТ #8	2024-02-15 10:59
MOT test number	670070742438
Result	✓ Passed
Next expiry date	2025-02-20
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2	2023-02-18 14:53
MOT test i	number	615757110623
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		(a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #6	2023-02-18 09:19	
MOT test number	599873858460	
Result	🗙 Failed	
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Fail Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)	))	

MOT #5		2022-02-21 11:50
MOT test	number	820705487083
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 235/60/18 (5.2.3 (e))	
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2021-02-10 11:09
MOT test number	259574647964
Result	✓ Passed
MOT #3	2020-11-23 15:38
MOT test number	598378983525
Result	✓ Passed

MOT #2	2020-07-02 11:34
MOT test number	928472093109
Result	✓ Passed





MOT #1	2019-02-07 14:47
MOT test number	329608891363
Result	✓ Passed



Tax & MOT check

<b>Tax due:</b> 1 March 2025	✓ Taxed	<b>Expires:</b> 20 February 2025	✓ МОТ
Tax status			Valid until 1 March
Days left			307
MOT expiry date			20 February 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARAPE
Туре	
Damage 2	AMPL
	F Store
Date	1. E
Category	ame
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
*********	
********	
******	
*********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-04-15
Last registration	2024-02-15
Complete history	See info



Registration #1	2016-04-15	20 mi
Registration #2	2019-02-07	28.317 mi
Registration #3	2020-07-02	41.665 mi
Registration #4	2020-11-23	44.817 mi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10.300 est

More info >





### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
\$0569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1750 kg
Max. allowed weight	2485 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	1746148