



report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Blue
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 2

Date	2022-03-12
Pictures	31
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-11-05
Pictures	9
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-12-08
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	9
Total items failed	3

MOT #13 2023-12-08 08:55**MOT test number** 798559574955**Result** ✓ Passed**Next expiry date** 2024-12-08

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2022-12-01 14:42**MOT test number** 599295287174**Result** ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2022-12-01 10:23**MOT test number** 528450232182**Result** ✗ Failed

- DANGEROUS** Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2021-11-23 13:00**MOT test number** 712188157048**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-11-17 19:53**MOT test number** 967143496908**Result** ✓ Passed**MOT #8** 2020-11-17 19:53**MOT test number** 460690446843**Result** ✗ Failed**Pass with rectification** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt BOOT ADRIFT (6.1.7 (g) (ii))**MOT #7** 2019-12-09 14:12**MOT test number** 536254945942**Result** ✓ Passed**MOT #6** 2019-01-14 09:28**MOT test number** 667846121041**Result** ✓ Passed**MOT #5** 2019-01-14 09:28**MOT test number** 185779678107**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #4** 2018-01-20 13:59**MOT test number** 190390113261**Result** ✓ Passed



MOT #3	2017-01-06 14:20
MOT test number	939343562336
Result	✓ Passed
MOT #2	2015-12-22 11:39
MOT test number	898423954910
Result	✓ Passed
MOT #1	2015-12-21 09:56
MOT test number	352769808714
Result	✗ Failed
Fail	Offside Front Fluid suspension unit leaking (2.4.D.2)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
8 December 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	8 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LD62GMF
Plate since	2019-03-28
Current registration	LD62GMF
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-01-11
Last registration	2023-12-08
Complete history	See info



Registration #1	2013-01-11	14 mi
Registration #2	2015-12-21	8.670 mi
Registration #3	2015-12-22	8.670 mi
Registration #4	2017-01-06	18.039 mi
Registration #5	2018-01-20	32.087 mi
Registration #6	2019-01-14	35.291 mi
Registration #7	2019-01-14	35.291 mi
Registration #8	2019-12-09	39.745 mi
Registration #9	2019-12-09	39.745 mi
Registration #10	2019-12-09	39.745 mi
Registration #11	2019-12-09	39.745 mi
Registration #12	2019-12-09	39.745 mi
Registration #13	2019-12-09	39.745 mi
Registration #14	2019-12-09	39.745 mi
Registration #15	2019-12-09	39.745 mi
Registration #16	2019-12-09	39.745 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

