



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	White
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 4


Date	2022-11-19
Pictures	48
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 3

Date	2021-12-30
Pictures	11
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date	2021-06-13
Pictures	10
Listing price	View report




source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2021-06-08
Pictures	24

Listing price

[View report](#)



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-11-13
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #10 2023-11-01 08:39

MOT test number 347720354436

Result ✓ Passed

Next expiry date 2024-11-13

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2022-11-14 16:39

MOT test number 241510323915

Result ✓ Passed

MOT #8 2022-05-06 16:30

MOT test number 815246406305

Result ✓ Passed

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #7** 2022-05-05 17:49**MOT test number** 372876772029**Result** ✗ Failed**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**MOT #6** 2021-05-14 09:06**MOT test number** 367651632522**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine, under tray and floor covers fitted**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #5** 2020-05-27 09:02**MOT test number** 357438156738**Result** ✓ Passed**Advice** Covers fitted**MOT #4** 2019-04-26 08:50**MOT test number** 419496173239**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #3** 2018-05-21 16:12**MOT test number** 834770204111**Result** ✓ Passed**Advice** Engine, under tray and floor covers fitted**MOT #2** 2018-05-21 11:39**MOT test number** 607434493442**Result** ✗ Failed**Advice** Nearside Front Nail in tyre**Minor** Nearside Front Windscreen wiper blade defective rubber split (3.4 (b) (i))**Advice** Engine, under tray and floor covers fitted**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #1** 2017-05-12 15:16**MOT test number** 230006463358**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
13 November 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	13 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EJ14LNH
Plate since	2019-09-28
Current registration	EJ14LNH
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-05-22
Last registration	2023-11-01
Complete history	See info



Registration #1	2014-05-22	28 mi
Registration #2	2017-05-12	27.088 mi
Registration #3	2018-05-21	33.426 mi
Registration #4	2018-05-21	33.432 mi
Registration #5	2019-04-26	44.044 mi
Registration #6	2020-05-27	52.451 mi
Registration #7	2021-05-14	63.502 mi
Registration #8	2022-05-22	75.277 mi
Registration #9	2023-05-22	86.277 mi
Registration #10	2023-05-22	97.277 mi
Registration #11	2023-05-22	108.277 mi
Registration #12	2023-05-22	119.277 mi
Registration #13	2023-05-22	130.277 mi
Registration #14	2023-05-22	141.277 mi
Registration #15	2023-05-22	152.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1679 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HAEZ040042