





report date: 2024-03-29

General information

Make	BMW
Model	X6 XDRIVE40D M SPORT
Colour	Grey
Year of manufacture	2018
Top speed	149 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.8 mpg
CO2 emission	183 g/km
CO2 label	I



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-10

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-11-12
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	7
Total items failed	3

MOT #5	2023-11-13 15:34
MOT test number	540608709342
Result	✓ Passed
Next expiry date	2024-11-12

MOT #4	2023-11-13 14:51
MOT test number	546184380337
Result	X Failed
Fail Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))	

MOT #3		2022-11-08 11:09
MOT test	number	124123637979
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))	

MOT #2	2021-11-01 08:43
MOT test number	733700757733
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-09-10 10:59

MOT test number 875821111851

Result

★ Failed

Advice Nearside Rear Other passenger door pillar deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Nearside Rear Body component damaged but not likely to cause injury

Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 12 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	12 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

LG68FDN

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this BMW had different number plates. obser of plates

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-09-11
Last registration	2023-11-13
Complete history	See info



Registration #1	2018-09-11	7 mi
Registration #2	2021-09-10	32.420 mi
Registration #3		11.777 es
Registration #4	2021-11-01	32.544 mi
Registration #5		11.777 mi
Registration #6		11.777 44
Registration #7		11.777 no

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1989 mm
Height	1702 mm
Length	4909 mm
Wheel base	2933 mm
Kerb weight	2105 kg
Max. allowed weight	2820 kg

Additional information

Fuel tank capacity	85 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	11/11

Number of axles 2

Engine number 55085067