



report date: 2024-03-28

General information

Make	FORD
Model	KUGA LX TDCI
Colour	Grey
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

<b>MOT #13</b>	2020-05-22 11:23
<b>MOT test number</b>	441397693594
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-05-21
<b>Advice</b>	O/s/ wing mirror outer case has damage
<b>Advice</b>	N/s/r lower fog lamp has damage
<b>Advice</b>	Clutch anti slip rubber pad missing
<b>Advice</b>	Small chips / cracks in windscreen

<b>MOT #12</b>	2019-04-26 11:27
<b>MOT test number</b>	154905477965
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
<b>Advice</b>	Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
<b>Advice</b>	Slight damage nearside rear lower light lens
<b>Advice</b>	Under tray fitted
<b>Advice</b>	Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
<b>Advice</b>	Engine covers fitted

<b>MOT #11</b>	2018-04-21 08:58
<b>MOT test number</b>	932748265127
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2017-04-28 09:51**MOT test number** 398056165658**Result** ✓ Passed**MOT #9** 2017-04-28 09:51**MOT test number** 826823227114**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Brake pedal anti-slip provision missing (3.3.A.1b)**MOT #8** 2016-04-29 10:56**MOT test number** 203621421186**Result** ✓ Passed**MOT #7** 2015-05-01 09:38**MOT test number** 279061125409**Result** ✓ Passed**Notice** N/s/r tyre tread wearing slightly uneven**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-05-10 08:49**MOT test number** 877400334187**Result** ✓ Passed**MOT #5** 2013-04-25 11:55**MOT test number** 535155513175**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #4** 2013-04-25 11:55**MOT test number** 269095213139**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #3** 2012-05-08 09:18**MOT test number** 366059722132**Result** ✓ Passed**MOT #2** 2011-10-25 11:15**MOT test number** 399238191401**Result** ✓ Passed**MOT #1** 2011-10-25 11:15**MOT test number** 557528891246**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-11-13
Last registration	2020-05-22
Complete history	<a href="#">See info</a>



Registration #1	2008-11-13	19 mi
Registration #2	2011-10-25	66.314 mi
Registration #3	2012-05-08	77.291 mi
Registration #4	2013-04-25	83.453 mi
Registration #5	2014-05-10	90.736 mi
Registration #6	2015-05-01	96.911 mi
Registration #7	2016-04-29	103.390 mi
Registration #8	2017-05-22	110.277 mi
Registration #9	2018-05-22	117.277 mi
Registration #10	2019-05-22	124.277 mi
Registration #11	2020-05-22	131.277 mi
Registration #12	2021-05-22	138.277 mi
Registration #13	2022-05-22	145.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	8R41969