



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Orange
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-19
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-24
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	16
Total items failed	5

MOT #14	2024-04-24 13:47
MOT test number	321601164952
Result	✓ Passed
Next expiry date	2025-04-24
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #13	2024-04-23 08:43
MOT test number	857767513434
Result	✗ Failed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Fail	Offside Front Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #12** 2023-04-24 09:53**MOT test number** 407939814786**Result** ✓ Passed**MOT #11** 2022-04-25 16:00**MOT test number** 678451578605**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2021-02-27 13:27**MOT test number** 180193849753**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-03-04 10:04**MOT test number** 381195889354**Result** ✓ Passed**MOT #8** 2019-03-18 12:17**MOT test number** 792658582273**Result** ✓ Passed**MOT #7** 2018-03-23 09:26**MOT test number** 302437219395**Result** ✓ Passed

**MOT #6** 2017-03-14 09:43**MOT test number** 159988536563**Result** ✓ Passed**MOT #5** 2016-03-12 11:20**MOT test number** 640276865406**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened Inner (3.5.1i)**MOT #4** 2015-03-25 17:07**MOT test number** 256834385088**Result** ✓ Passed**MOT #3** 2014-06-02 10:00**MOT test number** 236853754425**Result** ✓ Passed**Notice** Osf+nsf tyres low on edges**MOT #2** 2013-06-10 14:15**MOT test number** 727161763134**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



MOT #1	2013-06-10 14:15
MOT test number	265511663193
Result	✗ Failed
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Nearside Headlamp aim too high and too far to the right. (1.8)
Pass with rectification	Offside Headlamp aim too high (1.8)
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
24 April 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YY100LW
Plate since	2024-03-29
Current registration	 YY100LW
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-30
Last registration	2024-04-24
Complete history	See info



Registration #1	2010-06-30	17 mi
Registration #2	2013-06-10	26.524 mi
Registration #3	2014-06-02	37.553 mi
Registration #4	2015-03-25	45.712 mi
Registration #5	2016-03-12	48.862 mi
Registration #6	2017-03-14	52.095 mi
Registration #7	2018-03-23	55.070 mi
Registration #8	2019-03-18	61.124 mi
Registration #9	2020-03-20	65.377 mi
Registration #10	2021-03-20	69.377 mi
Registration #11	2022-03-20	73.377 mi
Registration #12	2023-03-20	77.377 mi
Registration #13	2024-03-20	81.377 mi
Registration #14	2025-03-20	85.377 mi
Registration #15	2026-03-20	89.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Engine number	CGP 038843