



GXI9YUR


report date: 2024-03-29

General information

Make	LEXUS
Model	IS 300H SPORT
Colour	Silver
Year of manufacture	2019
Top speed	125 mph
Gearbox	1 speed automatic

Engine & fuel consumption

Power	220 BHP
Max. torque	520 Nm at 4.200 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	45.6 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-09
Pictures	19
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-18
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #4	2024-03-06 11:18
MOT test number	326794331189
Result	✓ Passed
Next expiry date	2025-03-18
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))

MOT #3	2024-03-06 09:19
MOT test number	771696437486
Result	✗ Failed
DANGEROUS	Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure Cords exposed (5.2.3 (d) (ii))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))
DANGEROUS	Offside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure Cords exposed (5.2.3 (d) (ii))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #2** 2023-03-07 09:13**MOT test number** 687860924664**Result** ✓ Passed

- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords Outer Sidewall (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer Sidewall (5.2.3 (d) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #1 2022-03-04 12:22**MOT test number** 357456458036**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
18 March 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	F
First licence fee (12 months)	£ 175,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-03-19
Last registration	2024-03-06
Complete history	See info



Registration #1	2019-03-19	29 mi
Registration #2	2019-03-19	25.365 mi
Registration #3	2022-03-04	25.365 mi
Registration #4	2022-03-04	25.365 mi
Registration #5	2022-03-04	25.365 mi
Registration #6	2022-03-04	25.365 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4680 mm
Max. allowed weight	2145 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	2AR2066153