



TOYOTA

E875E00

report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA GTI 16
Colour	Red
Year of manufacture	1988
Top speed	122 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	135 Nm at 5.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol



LABEL UNKNOWN



MOT history

MOT expiry date	2020-09-16
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	0
Total items failed	7

MOT #19	2019-09-03 07:51
MOT test number	149110881061
Result	✓ Passed
Next expiry date	2020-09-16

MOT #18	2018-09-17 09:48
MOT test number	215427651018
Result	✓ Passed

MOT #17	2017-09-05 10:24
MOT test number	905977418484
Result	✓ Passed

MOT #16	2016-08-25 11:17
MOT test number	909516699215
Result	✓ Passed

MOT #15	2015-08-20 15:02
MOT test number	230348823485
Result	✓ Passed

**MOT #14** 2014-08-19 08:49**MOT test number** 609511134262**Result** ✓ Passed**MOT #13** 2014-08-19 08:49**MOT test number** 595551734217**Result** ✗ Failed**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #12** 2013-08-21 08:47**MOT test number** 385653933429**Result** ✓ Passed**MOT #11** 2013-08-21 08:47**MOT test number** 818873533237**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #10** 2012-08-17 09:00**MOT test number** 535190732236**Result** ✓ Passed**MOT #9** 2011-08-23 10:54**MOT test number** 686895831271**Result** ✓ Passed**MOT #8** 2011-08-23 10:54**MOT test number** 577165531202**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp adversely affected by the operation of another lamp (1.2.1f)

**MOT #7** 2010-08-23 11:35**MOT test number** 453905930297**Result** Passed**MOT #6** 2010-08-23 08:54**MOT test number** 304355130468**Result** Failed**Fail** Nearside Front Front constant velocity joint gaiter split (2.5.C.1a)**Fail** Offside Front Front constant velocity joint gaiter split (2.5.C.1a)**MOT #5** 2009-08-24 14:51**MOT test number** 133106439202**Result** Passed**MOT #4** 2009-08-24 12:07**MOT test number** 373586639220**Result** Failed**Fail** Nearside Front Steering rack gaiter split (2.2.D.2d)**Fail** Nearside Front Front constant velocity joint gaiter split (2.5.C.1a)**MOT #3** 2008-09-03 09:04**MOT test number** 602777948253**Result** Passed**MOT #2** 2007-09-07 09:12**MOT test number** 354050057463**Result** Passed



MOT #1	2006-09-06 08:49
MOT test number	294439346291
Result	✓ Passed



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	E875E00
Plate since	2019-03-28
Current registration	E875E00
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	1988-05-25
Last registration	2019-09-03
Complete history	See info



Registration #1	1988-05-25	18 mi
Registration #2	2006-09-06	41.067 mi
Registration #3	2007-09-07	41.941 mi
Registration #4	2008-09-03	42.782 mi
Registration #5	2009-08-24	43.621 mi
Registration #6	2009-08-24	43.621 mi
Registration #7	2010-08-23	44.468 mi
Registration #8	2010-08-23	44.468 mi
Registration #9	2011-08-23	45.388 mi
Registration #10	2012-08-23	46.308 mi
Registration #11	2013-08-23	47.228 mi
Registration #12	2014-08-23	48.148 mi
Registration #13	2015-08-23	49.068 mi
Registration #14	2016-08-23	50.000 mi
Registration #15	2017-08-23	51.000 mi
Registration #16	2018-08-23	52.000 mi
Registration #17	2019-08-23	53.000 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1655 mm
Height	1360 mm
Length	3995 mm

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	4A1216682