



PEUGEOT



MAI2VSD

report date: 2024-03-28

General information

Make	PEUGEOT
Model	PARTNER HDI S L1 850
Colour	White
Year of manufacture	2012
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	56.5 mpg
Consumption combined	52.3 mpg



LABEL UNKNOWN



## MOT history

MOT expiry date	2023-12-15
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #9 2022-12-16 08:57

MOT test number 323136265993

Result ✓ Passed

Next expiry date 2023-12-15

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view crack (3.2 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2021-08-10 10:45

MOT test number 729872211270

Result ✓ Passed

MOT #7 2020-08-19 14:29

MOT test number 616482233649

Result ✓ Passed

**MOT #6** 2020-08-13 15:12**MOT test number** 815559371767**Result** ✗ Failed**Advice** EXHAUST HEAT SHIELD INSECURE**Fail** Windscreen washer not working (3.5 (a))**MOT #5** 2019-11-23 14:30**MOT test number** 667208922091**Result** ✓ Passed**MOT #4** 2019-11-22 17:39**MOT test number** 751279486878**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #3** 2017-11-04 14:49**MOT test number** 649702503828**Result** ✓ Passed**MOT #2** 2016-07-12 14:17**MOT test number** 901068813365**Result** ✓ Passed**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2015-03-17 14:56
MOT test number	468116175032
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 May 2023

✕  
MOT

Expired:  
15 December 2023

Tax status	Expired at 31 May 2023
Days left	335 days too late
MOT expiry date	15 December 2023
Full MOT history	<a href="#">See MOT history</a>



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2024-03-28
Current registration	XXXXX
Plate since	2024-03-28

More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2012-03-29
Last registration	2022-12-16
Complete history	<a href="#">See info</a>



Registration #1	2012-03-29	26 mi
Registration #2	2015-03-17	91.246 mi
Registration #3	2016-07-12	106.926 mi
Registration #4	2017-11-04	111.576 mi
Registration #5	2019-11-22	111.610 mi
Registration #6	2020-05-20	111.610 mi
Registration #7	2020-05-20	111.610 mi
Registration #8	2020-05-20	111.610 mi
Registration #9	2020-05-20	111.610 mi
Registration #10	2022-12-16	111.610 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1810 mm
Height	1834 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1440 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	JBEM0015681