



report date: 2024-03-28

General information

| | |
|---------------------|-------------------------------|
| Make | FIAT |
| Model | GRAND PUNTO 16V DYNAMIC SPORT |
| Colour | Red |
| Year of manufacture | 2007 |
| Top speed | 111 mph |
| 0 - 60 mph | 11.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 94 BHP |
| Max. torque | 125 Nm at 4.500 rpm |
| Engine capacity | 1.368 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 33.6 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 142 g/km |
| CO2 label | F |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-29 |
| Pictures | 4 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-02-12 |
| MOT pass rate | 67 % |
| MOT passed | 12 |
| Failed MOT tests | 6 |
| Total advice items | 43 |
| Total items failed | 13 |

MOT #18 2022-02-03 16:51

MOT test number 313719169268

Result ✓ Passed

Next expiry date 2023-02-12

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #17 2022-02-03 12:26

MOT test number 804370126490

Result ✗ Failed

Advice Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt

Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Emissions not tested (8.2.1.2 (d))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #16 2021-01-20 14:29

MOT test number 161822515256

Result ✓ Passed

**MOT #15** 2020-01-16 10:05**MOT test number** 766050101521**Result** ✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2019-02-13 17:30**MOT test number** 186386537867**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2019-02-13 15:09**MOT test number** 774098388006**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a))

MOT #12 2017-08-14 16:06**MOT test number** 569451556705**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Mileage not showing on dash. Found correct mileage using Fiat tool.
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #11** 2017-08-07 11:00**MOT test number** 776233325422**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Mileage not showing on dash. Found correct mileage using Fiat tool.**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #10** 2016-08-30 13:34**MOT test number** 307058277887**Result** ✓ Passed**Advice** Oil leak Gearbox**MOT #9** 2016-08-30 08:23**MOT test number** 186436926368**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Advice** Oil leak Gearbox

**MOT #8** 2015-09-02 11:03**MOT test number** 157263500113**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #7 2014-09-01 14:59**MOT test number** 396424944250**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #6 2014-09-01 14:59**MOT test number** 849774344260**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Pass with rectification** Offside Headlamp aim too low (1.8)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #5** 2013-08-29 11:41**MOT test number** 486121843223**Result** ✓ Passed**Notice** Oil leak**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Exhaust corroded.**MOT #4** 2012-08-31 12:28**MOT test number** 977824142286**Result** ✓ Passed**MOT #3** 2011-08-26 09:33**MOT test number** 927958031248**Result** ✓ Passed**Notice** Oil leak**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2011-08-26 09:33**MOT test number** 898318031223**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Notice** Oil leak**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Notice** Child seat fitted not allowing full inspection of adult belt




| | |
|-----------------|---|
| MOT #1 | 2010-09-01 15:07 |
| MOT test number | 102654740205 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FIAT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2007-10-19 |
| Last registration | 2022-02-03 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-10-19 | 14 mi |
| Registration #2 | 2010-09-01 | 14.339 mi |
| Registration #3 | 2011-08-26 | 20.290 mi |
| Registration #4 | 2012-08-31 | 30.883 mi |
| Registration #5 | 2013-08-29 | 41.424 mi |
| Registration #6 | 2014-09-01 | 50.851 mi |
| Registration #7 | 2015-09-02 | 58.340 mi |
| Registration #8 | 2017-08-07 | 80.671 mi |
| Registration #9 | 2019-05-20 | 95.377 mi |
| Registration #10 | 2020-05-20 | 101.377 mi |
| Registration #11 | 2021-05-20 | 107.377 mi |
| Registration #12 | 2022-05-20 | 113.377 mi |
| Registration #13 | 2023-05-20 | 119.377 mi |
| Registration #14 | 2024-05-20 | 125.377 mi |
| Registration #15 | 2025-05-20 | 131.377 mi |
| Registration #16 | 2026-05-20 | 137.377 mi |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1687 mm |
| Height | 1490 mm |
| Length | 4030 mm |
| Wheel base | 2510 mm |
| Kerb weight | 1060 kg |
| Max. allowed weight | 2635 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1134831 |