





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT EXECUTIVE TDI BLUEMOTION TECHNOLOGY
Colour	Grey
Year of manufacture	2014
Gearbox	6 speed Manual

Engine & fuel consumption

Power	175 BHP
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-05-25

Pictures 46

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-23
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	3

MOT #8	2023-05-13 08:11	
MOT test number	507357435108	
Result	✓ Passed	
Next expiry date	2024-05-23	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement on back of arm (5.3.4 (a) (i))		
Advice Tyre worn close to legal limit/worn on edge both front tyres wearing in	nner edges (5.2.3 (e))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in e of arm (5.3.4 (a) (i))	excessive movement on back	

MOT #7	2022-05-16 14:10
MOT test number	957355347424
Result	√ Passed
Advice Coolant leak	

MOT #6	2021-05-24 11:38
MOT test number	527772663719
Result	✓ Passed
MOT #5	2020-11-10 13:39
MOT test number	721961464549
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #4 2020-11-09 14:45

MOT test number 833223976199

Result X Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3 2019-05-03 08:43

MOT test number 969263565984

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2018-05-02 09:41

MOT test number 963811656438

Result

Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2017-05-11 08:47

MOT test number 340577739722

Result

Passed

Advice Nearside Rear Nail in tyre

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	23 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Tyne	

Damage 2	
Date	
Category	
Туре	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK SIP
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-05-29
Last registration	2023-05-13
Complete history	See info



Registration #1	2014-05-29	27 mi
Registration #2	2017-05-11	35.418 mi
Registration #3	2018-05-02	61.767 mi
Registration #4	2019-05-03	84.321 mi
Registration #5	2020-11-09	109.320 mi
Registration #6		11.777 es
Registration #7		71.777 es
Registration #7 Registration #8		17.777 44
-		11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1470 mm
Length	4769 mm
Wheel base	2712 mm
Kerb weight	1534 kg
Max. allowed weight	2090 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
CarChock co.uk	nago 11/11

CarCheck.co.uk page 11/11

Engine number

CFGC574229