





General information

| Make ME | RCEDES |
|-------------------------|----------------|
| Model ML | ML 350 |
| Colour Silv | /er |
| Year of manufacture 200 | 03 |
| Top speed 128 | 8 mph |
| 0 - 60 mph 8.7 | seconds |
| Gearbox 5 s | peed automatic |

Engine & fuel consumption

| Power | 245 BHP |
|-------------------------|---------------------|
| Max. torque | 350 Nm at 3.500 rpm |
| Engine capacity | 3.724 сс |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 14.6 mpg |
| Consumption extra urban | 25.7 mpg |
| Consumption combined | 20.0 mpg |
| CO2 emission | 305 g/km |
| CO2 label | М |





MOT history

| MOT expiry date | 2020-10-23 |
|--------------------|------------|
| MOT pass rate | 62 % |
| MOT passed | 13 |
| Failed MOT tests | 8 |
| Total advice items | 23 |
| Total items failed | 11 |

| MOT #21 | 2019-10-09 10:02 |
|---|------------------|
| MOT test number | 117231171981 |
| Result | 🗸 Passed |
| Next expiry date | 2020-10-23 |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |

| MOT #20 | | 2019-10-09 07:50 |
|----------|---|------------------|
| MOT test | number | 254553257200 |
| Result | | 🗙 Failed |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| MAJOR | Electronic power steering warning lamp indicates a system malfunction (2.6 (a)) | |
| MAJOR | Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| MAJOR | Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a)) | |

| MOT #19 | | 2018-10-24 10:38 |
|----------|--|------------------|
| MOT test | number | 248936890892 |
| Result | | ✓ Passed |
| Advice | Rear shock abs corroded | |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |





| MOT #18 | 2018-10-19 07:58 |
|--|---------------------|
| MOT test number | 958701613765 |
| Result | 🗙 Failed |
| MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reac (5.2.3 (d) (i)) | h the ply or cords |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| DANGEROUS Stop lamp(s) all not working (4.3.1 (a) (iii)) | |
| MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach (5.2.3 (d) (i)) | the ply or cords |
| MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach (5.2.3 (d) (i)) | the ply or cords |
| Advice Rear shock abs corroded | |
| MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to read (5.2.3 (d) (i)) | h the ply or cords: |

| MOT #17 | 2017-09-21 11:17 |
|-----------------|------------------|
| MOT test number | 914116864985 |
| Result | ✓ Passed |
| | |
| MOT #16 | 2016-10-19 14:18 |
| MOT test number | 312515522585 |
| Result | ✓ Passed |
| | |
| MOT #15 | 2015-03-13 08:12 |
| MOT test number | 327262075017 |
| | |

🗸 Passed





| MOT #14 | 2015-03-11 10:51 |
|---|------------------|
| MOT test number | 977060975008 |
| Result | 🗙 Failed |
| Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c) Notice Eml lamp on | |
| Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2) | |
| | 2012 00 20 11 12 |
| MOT #13 | 2013-08-29 11:12 |
| MOT test number | 215191343281 |
| Result | ✓ Passed |
| | |

| MOT #12 | 2013-08-28 11:12 |
|--|------------------|
| MOT test number | 849260943230 |
| Result | 🗙 Failed |
| Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2) | |
| Advice Nearside Front suspension has slight play in a lower suspension ball joint (2. | 5.B.1a) |
| Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3) | |
| Fail Offside Rear position lamp(s) not working (1.1.A.3b) | |
| Fail Rear registration plate deteriorated (6.3.1d) | |

| MOT #11 | 2012-08-20 11:04 |
|---|------------------|
| MOT test number | 299423432213 |
| Result | ✓ Passed |
| Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d) | |



RX03XKG report date: 2024-03-29

| MOT #10 | 2012-08-20 11:04 |
|---|------------------|
| MOT test number | 328513732417 |
| Result | 🗙 Failed |
| Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d) | |
| Pass with rectification Offside Stop lamp not working (1.2.1b) | |

| МОТ #9 | 2011-09-01 10:33 |
|-----------------|------------------|
| MOT test number | 307034341416 |
| Result | ✓ Passed |

| MOT #8 | | 2011-09-01 10:33 |
|-------------------------|---|------------------|
| MOT test number | | 959194941218 |
| Result | | × Failed |
| Pass with rectification | Nearside Stop lamp not working (1.2.1b) | |

| MOT #7 | 2010-08-31 11:13 |
|-----------------|------------------|
| MOT test number | 771563240278 |
| Result | ✓ Passed |

| MOT #6 | 2010-08-27 12:02 |
|---|------------------|
| MOT test number | 420899530291 |
| Result | 🗙 Failed |
| Fail Nearside Rear coil spring fractured (2.4.C.1a) | |
| Advice Front suspension has slight play in a lower suspension ball joint (2.5.B.1a) | |
| Fail Offside Rear coil spring fractured (2.4.C.1a) | |
| Notice Rear number plate poor condition | |





| МОТ #5 | 2009-08-20 10:17 |
|---|---------------------------|
| MOT test number | 331532039474 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2008-08-22 16:14 |
| MOT test number | 604715838242 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2007-08-09 10:24 |
| MOT test number | 401131627247 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2007-08-08 15:43 |
| MOT test number | 470530027284 |
| Result | × Failed |
| Notice N/s front tyre worn inner edge | |
| Fail Offside Front Tyre has a cut in excess of the requirements deep enough (4.1.D.1a) | to reach the ply or cords |
| MOT #1 | 2006-03-07 12:33 |

| MOT test | number | 552046866042 |
|----------|--|--------------|
| Result | | ✓ Passed |
| Advice | Nearside Rear Brake pad(s) wearing thin (3.5.1g) | |
| Advice | Offside Rear Brake pad(s) wearing thin (3.5.1g) | |



Tax & MOT check

| X Untaxed Tax expired: 1 November 2020 | X MOT Expired: 23 October 2020 |
|---|---|
| Tax status | Expired at 1 November 2020 |
| Days left | 1276 days too late |
| MOT expiry date | 23 October 2020 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 48 |
|---|------------|
| Band | К |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | VAMPLE |
| Date | |
| Category | AMP |
| Туре | |

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|---|-------------|
| | |
| | |
| | |
| | |
| ******* | |
| | More info > |
| Plate changes See in this check if this MERCEDES had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 20 |
| First mileage registration | 2003-03-18 |
| Last registration | 2019-10-09 |
| Complete history | See info |



| Registration #1 | 2003-03-18 | 18 mi |
|------------------|------------|------------|
| Registration #2 | 2006-03-07 | 20.113 mi |
| Registration #3 | 2007-08-08 | 27.724 mi |
| Registration #4 | 2007-08-09 | 27.759 mi |
| Registration #5 | 2008-08-22 | 33.905 mi |
| Registration #6 | 2009-08-20 | 38.347 mi |
| Registration #7 | 2010-08-27 | 41.432 mi |
| Registration #8 | 2010-08-31 | 41.459 mi |
| Registration #9 | 2011-09-01 | 44.174 mi |
| Registration #10 | 2012-08-20 | 46.224 mi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |
| Registration #16 | | 11.777 esi |
| Registration #17 | | 11.777 mi |
| Registration #18 | | 11.777 est |
| Registration #19 | | 11.777 mi |
| Registration #20 | | 11.117 mi |

More info \rightarrow



Dimensions & weight

| Width | 2190 mm |
|------------------------|---------|
| Height | 1820 mm |
| Length | 4710 mm |
| Wheel base | 2820 mm |
| Kerb weight | 2185 kg |
| Additional information | |

Fuel tank capacity83 IFuel deliveryMulti-Point InjectionNumber of doors5Number of axles2Engine number11297031402890