





General information

| Make | VOLVO |
|---------------------|----------------------|
| Model | XC60 T5 R-DESIGN AWD |
| Colour | Black |
| Year of manufacture | 2019 |
| Top speed | 137 mph |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 246 BHP |
|----------------------|---------------------|
| Max. torque | 350 Nm at 1.800 rpm |
| Engine capacity | 1.969 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption combined | 30.1 mpg |
| CO2 emission | 173 g/km |
| CO2 label | Н |





Internet history

Entry 1

Date Pictures 2022-02-02

50

Listing price

View report









source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-01-10 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 3 |
| Total items failed | 0 |

| MOT #3 | 2024-01-09 13:15 |
|------------------|------------------|
| MOT test number | 800439615255 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-10 |

| MOT #2 | | 2023-01-10 12:00 |
|--|--|------------------|
| MOT test | number | 213354928098 |
| Result | | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge tyre starting to crack (5.2.3 (e)) | | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge tyre starting to crack (5.2.3 (e)) | | (5.2.3 (e)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #1 | 2022-01-07 10:14 |
|-----------------|------------------|
| MOT test number | 438965616640 |
| Result | ✓ Passed |



Tax & MOT check

| √ Taxed | ✓ MOT |
|--------------------------|-----------------------------|
| Tax due: 1 March 2025 | Expires: 10 January 2025 |
| Tax status | Valid until 1 March |
| Days left | 307 |
| MOT expiry date | 10 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|--------------|
| Band | J |
| First licence fee (12 months) | £ 1.040,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------------|
| Date | FEIDO |
| Category | Anne |
| Туре | K K |
| Damage 2 | AMPLE |
| Damage 2 | e et - I - I |
| Date | S. |
| Category | AMPT |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second se | |
|---|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| | |
| Current registration | |
| Current registration Pate since | |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles | |
|----------------------------|------------|--|
| Mileage registrations | 5 | |
| First mileage registration | 2019-01-11 | |
| Last registration | 2024-01-09 | |
| Complete history | See info | |



| Registration #1 | 2019-01-11 | 28 mi |
|-----------------|------------|------------|
| Registration #2 | 2022-01-07 | 11.613 mi |
| Registration #3 | | 11.777 esi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 mi |






Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 98% |
| Children | 87% |
| Pedestrian | 76% |
| Safety systems | 95% |
| Overall rating | 90% |
| Video | see crash video |



| Dimensions & weight | |
|------------------------|---------|
| Width | 1999 mm |
| Height | 1658 mm |
| Length | 4688 mm |
| Max. allowed weight | 2430 kg |
| Additional information | |
| Number of seats | 5 |
| Number of axles | 2 |

3075859

Engine number