



General information

Make	VOLKSWAGEN
Model	PASSAT R LINE TDI
Colour	Silver
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F





MOT history

MOT expiry date	2021-03-27
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #9	2020-03-13 15:04
MOT test number	732184889312
Result	✓ Passed
Next expiry date	2021-03-27
Advice	Offside front tyre worn slightly on inner edge.
Advice	Rear tyres have slightly uneven tread on inner edges.

MOT #8	2019-03-05 11:37
MOT test number	639281499997
Result	✓ Passed
Advice	Nearside Rear outer lamp lense cover broken

MOT #7	2018-03-14 11:15
MOT test number	898700611767
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6	2017-03-06 11:17
MOT test number	997997532350
Result	✓ Passed

**MOT #5** 2016-03-24 08:38**MOT test number** 356411354600**Result** ✓ Passed**Advice** Offside front tyre worn slightly on inner edge.**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner faces slightly corroded (3.5.1i)**MOT #4** 2015-03-26 08:38**MOT test number** 339975985000**Result** ✓ Passed**Advice** Nearside Side repeater has light sources not illuminating, but not more than 50% (1.4.A.2c)**MOT #3** 2014-02-28 08:22**MOT test number** 298649754084**Result** ✓ Passed**MOT #2** 2014-02-27 08:55**MOT test number** 406128354021**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2013-03-14 08:56**MOT test number** 275083273050**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
10 November 2020

✕
MOT

Expired:
27 March 2021

Tax status	Expired at 10 November 2020
Days left	1266 days too late
MOT expiry date	27 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GJ10OSW
Plate since	2024-03-28
Current registration	 GJ10OSW
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2010-03-27
Last registration	2020-03-13
Complete history	See info



Registration #1	2010-03-27	19 mi
Registration #2	2013-03-14	47.235 mi
Registration #3	2014-02-27	62.006 mi
Registration #4	2014-02-28	62.006 mi
Registration #5	2015-03-26	77.144 mi
Registration #6	2016-03-26	92.282 mi
Registration #7	2017-03-26	107.420 mi
Registration #8	2018-03-26	122.558 mi
Registration #9	2019-03-26	137.696 mi
Registration #10	2020-03-13	152.834 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 694229