



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-06
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-07
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	30
Total items failed	0

MOT #10	2023-11-08 12:33
MOT test number	205654940300
Result	✓ Passed
Next expiry date	2024-11-07
Advice	Front brake pads worn
Advice	Offside rear tyre inner edge worn and perished
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside front brake has slight bind
Advice	Nearside rear tyre perished
Advice	Rear brake pads worn
Advice	Both front tyres edges worn low

MOT #9	2022-11-01 14:25
MOT test number	354636146608
Result	✓ Passed
Advice	Both Rear Tyres Perished
Advice	Both Front Tyres Edges Slightly Worn

**MOT #8** 2022-10-20 14:23**MOT test number** 507670695906**Result** ✗ Failed**Advice** Both Rear Tyres Perished**Advice** Both Front Tyres Edges Slightly Worn**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #7** 2021-08-06 13:04**MOT test number** 343320864513**Result** ✓ Passed**MOT #6** 2021-08-04 15:13**MOT test number** 823670228068**Result** ✗ Failed**MAJOR** Offside Rear Seat belt not functioning as intended Will not come out enough to engage with buckle (7.1.2 (c))**MOT #5** 2021-02-15 11:41**MOT test number** 859239969653**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**MOT #4** 2020-02-12 13:32**MOT test number** 867633505384**Result** ✓ Passed**Advice** Rear shock absorber boots split**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front tyres worn on inner edges

**MOT #3** 2019-02-28 10:20**MOT test number** 751274843436**Result** ✓ Passed

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge bald (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge bald (5.2.3 (e))
- Advice** Items removed from driver's view prior to test
- Advice** Offside Rear Brake pad(s) wearing thin 1.5mm max (1.1.13 (a) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge bald (5.2.3 (e))

**MOT #2** 2018-02-16 14:27**MOT test number** 661263668684**Result** ✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #1** 2017-02-27 10:01**MOT test number** 456783030613**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Tyre worn close to the legal limit All 4 tyres (4.1.E.1)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
7 November 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	7 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 <b>VX14WUE</b>
Plate since	2019-09-29
Current registration	 <b>VX14WUE</b>
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-01
Last registration	2023-11-08
Complete history	<a href="#">See info</a>



Registration #1	2014-03-01	21 mi
Registration #2	2017-02-27	42.351 mi
Registration #3	2018-02-16	54.868 mi
Registration #4	2019-02-28	61.351 mi
Registration #5	2020-02-12	63.902 mi
Registration #6	2021-02-15	66.454 mi
Registration #7	2022-02-22	69.006 mi
Registration #8	2023-02-27	71.558 mi
Registration #9	2023-08-01	74.110 mi
Registration #10	2023-11-08	76.662 mi
Registration #11	2023-11-08	76.662 mi
Registration #12	2023-11-08	76.662 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	D4HBEU978607