



PFI2TJZ

report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | S60 D3 SE LUX |
| Colour | Grey |
| Year of manufacture | 2012 |
| Top speed | 130 mph |
| 0 - 60 mph | 9.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 350 Nm at 1.500 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 114 g/km |
| CO2 label | C |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-18 |
| Pictures | 20 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-20 |
| MOT pass rate | 90 % |
| MOT passed | 9 |
| Failed MOT tests | 1 |
| Total advice items | 20 |
| Total items failed | 4 |

| | |
|------------------|---|
| MOT #10 | 2023-07-18 07:22 |
| MOT test number | 875032750221 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-20 |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #9 | 2022-07-21 15:04 |
| MOT test number | 694783423194 |
| Result | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #8 | 2021-07-15 15:34 |
| MOT test number | 557488496028 |
| Result | ✓ Passed |
| Advice | Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm or lateral link front eye bush. (5.3.4 (a) (i)) |
| Advice | Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Tailing or lateral link arm front eye bush. (5.3.4 (a) (i)) |

**MOT #7**

2021-07-15 13:08

MOT test number

672686304132

Result**✗ Failed****Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement
Tailing or lateral link arm front eye bush. (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt
(2.1.3 (g) (ii))**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement
Trailing arm or lateral link front eye bush. (5.3.4 (a) (i))**MOT #6**

2020-07-21 15:04

MOT test number

101021254646

Result**✓ Passed****Advice** Offside Headlamp has a product on the lens but not seriously reducing light output Dip beam
(4.1.4 (b))**MOT #5**

2019-07-22 15:21

MOT test number

163332974439

Result**✓ Passed****Advice** Offside Headlamp has a product on the light source but not seriously reducing light output Dip
beam not as bright as nearside. (4.1.4 (b))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2018-07-24 12:32**MOT test number** 204851564263**Result** ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge Devoid of pattern on inside shoulder (5.2.3 (e))

MOT #3 2017-07-25 13:14**MOT test number** 765815143222**Result** ✓ Passed**MOT #2** 2016-08-05 11:09**MOT test number** 736568244708**Result** ✓ Passed

- Advice** Osf tyre worn on inner shoulder
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #1 2015-08-27 11:28**MOT test number** 451694757963**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
20 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 20 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-20 |
| Current registration | ***** |
| Plate since | 2019-06-20 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2012-08-09 |
| Last registration | 2023-07-18 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2012-08-09 | 21 mi |
| Registration #2 | 2015-08-27 | 26.865 mi |
| Registration #3 | 2016-08-05 | 34.618 mi |
| Registration #4 | 2017-07-25 | 42.396 mi |
| Registration #5 | 2018-07-24 | 49.934 mi |
| Registration #6 | 2019-07-22 | 57.433 mi |
| Registration #7 | 2020-07-20 | 65.277 mi |
| Registration #8 | 2021-07-19 | 73.277 mi |
| Registration #9 | 2022-07-18 | 81.277 mi |
| Registration #10 | 2023-07-18 | 89.277 mi |
| Registration #11 | 2024-03-28 | 97.277 mi |
| Registration #12 | 2024-03-28 | 105.277 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 98% |
| Children | 75% |
| Pedestrian | 88% |
| Safety systems | 100% |
| Overall rating | 92% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1802 mm |
| Height | 1445 mm |
| Length | 4369 mm |
| Wheel base | 2647 mm |
| Kerb weight | 1516 kg |
| Max. allowed weight | 2020 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1220500 |