





report date: 2024-03-29

General information

| Make | AUDI |
|---------------------|---------------------------------------|
| Model | A7 SPORTBACK TDI QUATTRO SE EXECUTIVE |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 150 mph |
| 0 - 100 km/h | 6.8 seconds |
| 0 - 60 mph | 6.8 seconds |
| Gearbox | 7 speed Semi-Automatic |

Engine & fuel consumption

| Power | 160 kW / 218 HP / 215 BHP |
|-------------------------|---------------------------|
| Max. torque | 500 Nm at 1.250 rpm |
| Engine capacity | 2.967 сс |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 136 g/km |
| CO2 label | Е |



CarCheck.co.uk page 1/10



| MO | T hi | istory | , |
|----|------|--------|---|
|----|------|--------|---|

| MOT expiry date | 2024-12-26 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 2 |
| Total items failed | 2 |

| MOT #8 | 2023-12-27 15:35 |
|------------------|------------------|
| MOT test number | 621223907019 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-26 |

| MOT #7 | 2022-07-28 14:39 |
|--|------------------|
| MOT test number | 382686462098 |
| Result | ✓ Passed |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #6 | 2021-06-19 11:00 |
|--|------------------|
| MOT test number | 688887863840 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2020-06-22 09:55 |
| MOT test number | 541398967187 |
| Result | ✓ Passed |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2. | 3 (e)) |

| MOT #4 | 2019-07-08 14:46 |
|-----------------|------------------|
| MOT test number | 146814988379 |
| Result | ✓ Passed |

CarCheck.co.uk page 2/10



MOT #3

MOT test number

870318199336

Result

Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii))

MOT #2 2018-05-30 15:35
MOT test number 818060874084

MOT #1 2018-05-30 09:33

MOT test number 614464713875

Result X Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 337 |
| MOT expiry date | 26 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



| Owr | 200 | oict | 001 |
|--------|-------|-------|-------------------------|
| T DVVI | 161 1 | 11151 | $\mathbf{n} \mathbf{v}$ |
| | | 1136 | . O i y |

| For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report | |
|--|--|
| | |
| manage of the same | |
| *************************************** | |
| *************************************** | |
| | |
| THE PARTY OF THE P | |
| | |
| *************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this AUDI had different number plates. | |
| | |
| Number of states | |
| | |
| Current registration | NK AND |
| Plate since | |
| Francis and Anthropia | NE |
| | OK SIE |
| Plate since | |
| | More info > |
| | More into > |

CarCheck.co.uk page 7/10



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2015-06-09 |
| Last registration | 2023-12-27 |
| Complete history | See info |



| Registration #1 | 2015-06-09 | 8 mi |
|-----------------|------------|-----------|
| Registration #2 | 2018-05-30 | 29.938 mi |
| Registration #3 | 2018-05-30 | 29.938 mi |
| Registration #4 | 2019-06-01 | 31.778 mi |
| Registration #5 | 2019-07-08 | 31.980 mi |
| Registration #6 | | 71.777 66 |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Dimensions & weight

| Width | 1911 mm |
|---------------------|---------|
| Height | 1420 mm |
| Length | 4974 mm |
| Wheel base | 2914 mm |
| Kerb weight | 1825 kg |
| Max. allowed weight | 2435 kg |

Additional information

| Fuel tank capacity | 73 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | CRTE012047 |

CarCheck.co.uk page 10/10