





report date: 2024-03-29

#### General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G



CarCheck.co.uk page 1/12



## Internet history


#### Entry 1

Date 2021-07-05

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-19
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #13	2023-07-14 15:33
MOT test number	349396174646
Result	✓ Passed
Next expiry date	2024-07-19

MOT #12		2022-07-20 12:08
MOT test	number	740444845811
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge on legal limit 245	/40/18 (5.2.3 (e))

MOT #11	2022-07-20 08:16
MOT test number	383507527594
Result	<b>×</b> Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge on legal limit 245  Fail Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))	5/40/18 (5.2.3 (e))

MOT #10	2021-07-20 12:13
MOT test number	773006624089
Result	<b>✓</b> Passed
Advice Advise n/s/r tyre has side wall splitting	

CarCheck.co.uk page 3/12



MOT #9

MOT test number

Sesult

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2019-12-20 09:52 **MOT test number** 187854883408 Result ✓ Passed MOT #7 2018-09-03 07:49 **MOT** test number 945394006769 Result ✓ Passed MOT #6 2017-09-25 08:33 **MOT test number** 780495609927 Result Passed **Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

 MOT #5
 2016-09-08 09:29

 MOT test number
 136579501845

 Result
 ✓ Passed

MOT #4

MOT test number

788021860912

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



MOT test number
618586964210

Result

Notice Under-trays fitted obscuring some underside components

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice N/s/f tyre wearing on inner treads

Notice Engine covers fitted obscuring some components in the engine bay

MOT #2		2013-09-16 09:54
MOT test	number	116299553232
Result		<b>✓</b> Passed
MOT #1		2012-09-06 11:49
MOT test	number	715110252244
Result		<b>✓</b> Passed
Notice	Items removed from driver's view prior to test	
Notice	SLIGHT DAMAGE TO FRONT TYRES OUTER SIDE WALLS	

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	19 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



VK59NXO

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
***************************************	
***************************************	
********	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-28
Last registration	2023-07-14
Complete history	See info



Registration #1	2009-09-28	14 mi
Registration #2	2012-09-06	11.224 mi
Registration #3	2013-09-16	20.107 mi
Registration #4	2014-09-23	30.199 mi
Registration #5	2015-09-04	38.639 mi
Registration #6	2016-09-08	47.849 mi
Registration #7	2017-09-25	56.139 mi
Registration #8	2018-09-03	62.812 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11,117 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



## Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

# Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12