



RENAULT



report date: 2024-03-29

General information

| | |
|---------------------|----------------------------|
| Make | RENAULT |
| Model | TRAFIC SL27DCI 100 SWB P/V |
| Colour | White |
| Year of manufacture | - |
| Top speed | 97 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 100 BHP |
| Max. torque | 240 Nm at 2.000 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.7 mpg |
| Consumption extra urban | 43.5 mpg |
| Consumption combined | 38.2 mpg |



LABEL UNKNOWN



Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-07-16 |
| Pictures | 6 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-02 |
| Pictures | 6 |
| Listing price | View report |



source: [autotrader.co.uk](#)

**MOT history****MOT #23** 2022-01-31 17:50**MOT test number** 779431327597**Result** ✓ Passed**Next expiry date** 2023-01-30

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

MOT #22 2022-01-29 13:45**MOT test number** 705324581999**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



| | |
|-----------------|---|
| MOT #21 | 2021-01-27 16:46 |
| MOT test number | 146032599140 |
| Result | ✓ Passed |
| Advice | Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) |

| | |
|-----------------|--|
| MOT #20 | 2019-12-23 11:20 |
| MOT test number | 327898263211 |
| Result | ✓ Passed |
| Advice | Nearside Rear Brake pipe corroded, covered in grease or other material to flexi hose (1.1.11 (c)) |
| Advice | Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Nearside Rear light cluster lens cracked |
| Minor | Offside Rear fog lamp lens defective which has no effect on emitted light (4.5.1 (b) (i)) |
| Advice | Offside Rear Brake pipe corroded, covered in grease or other material from flexi (1.1.11 (c)) |

**MOT #19**

2019-12-09 16:42

MOT test number

829407938042

Result**✗ Failed**

- Advice** Nearside Rear light cluster lens cracked
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to flexi hose (1.1.11 (c))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Minor** Offside Rear fog lamp lens defective which has no effect on emitted light (4.5.1 (b) (i))
- Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material from flexi (1.1.11 (c))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #18

2018-10-04 17:10

MOT test number

282678997125

Result**✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Both front tyres low on shoulders



| | |
|-----------------|--|
| MOT #17 | 2018-10-04 10:35 |
| MOT test number | 963954258049 |
| Result | ✗ Failed |
| Fail | Windscreen washer not working (3.5 (a)) |
| Fail | Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) |
| Fail | Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) |
| Fail | Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Advice | Both front tyres low on shoulders |
| Fail | Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) |

| | |
|-----------------|---|
| MOT #16 | 2017-09-21 12:53 |
| MOT test number | 388516938263 |
| Result | ✓ Passed |
| Advice | Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c) |
| Advice | Chuffing noise from engine |
| Advice | Nearside Rear Brake pipe slightly corroded (3.6.B.2c) |
| Advice | Clutch pedal low |

**MOT #15**

2017-09-20 08:16

MOT test number

409943089484

Result**✗ Failed**

- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Clutch pedal low
- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Chuffing noise from engine
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)
- Fail** Power steering pipe(s) or hose(s) leaking from a joint (2.3.3b)
- Advice** Engine oil on min mark
- Fail** Power steering inoperative (2.3.3a)

MOT #14

2016-09-27 17:32

MOT test number

202662256887

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Panhard rod corroded but not seriously weakened all 4 shocks (2.4.G.1)

**MOT #13** 2016-09-27 09:58**MOT test number** 997579080819**Result** ✗ Failed**Advice** Panhard rod corroded but not seriously weakened all 4 shocks (2.4.G.1)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Emissions not tested age of cambelt (7.4.B.1)**Fail** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2015-09-16 11:49**MOT test number** 566012796563**Result** ✓ Passed**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**MOT #11** 2015-09-16 11:49**MOT test number** 511063458982**Result** ✗ Failed**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Centre Stop lamp not working (1.2.1b)

**MOT #10** 2014-10-02 11:18**MOT test number** 615325274289**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-10-02 11:18**MOT test number** 679305174275**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #8** 2013-10-05 13:54**MOT test number** 586348173285**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2013-10-05 11:44**MOT test number** 767468673279**Result** ✗ Failed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #6** 2012-09-08 10:49**MOT test number** 306932652411**Result** ✓ Passed

**MOT #5** 2011-10-01 09:16**MOT test number** 479424471200**Result** ✓ Passed**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #4** 2011-10-01 09:16**MOT test number** 945244771292**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper blade insecure (8.2.2)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2010-09-15 15:31**MOT test number** 403208750285**Result** ✓ Passed**MOT #2** 2010-09-14 11:26**MOT test number** 883047750255**Result** ✗ Failed**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #1** 2009-09-19 12:20**MOT test number** 864012169285**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 2006-09-29 |
| Last registration | 2022-01-31 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-09-29 | 17 mi |
| Registration #2 | 2009-09-19 | 24.520 mi |
| Registration #3 | 2010-09-14 | 30.500 mi |
| Registration #4 | 2010-09-15 | 30.509 mi |
| Registration #5 | 2011-10-01 | 37.655 mi |
| Registration #6 | 2012-09-08 | 44.613 mi |
| Registration #7 | 2013-10-05 | 51.004 mi |
| Registration #8 | 2013-10-05 | 51.004 mi |
| Registration #9 | 2014-10-02 | 57.375 mi |
| Registration #10 | 2015-09-16 | 64.378 mi |
| Registration #11 | 2015-09-16 | 64.378 mi |
| Registration #12 | 2016-09-27 | 71.080 mi |
| Registration #13 | 2016-09-27 | 71.080 mi |
| Registration #14 | 2016-09-27 | 71.080 mi |
| Registration #15 | 2016-09-27 | 71.080 mi |
| Registration #16 | 2016-09-27 | 71.080 mi |
| Registration #17 | 2016-09-27 | 71.080 mi |
| Registration #18 | 2016-09-27 | 71.080 mi |
| Registration #19 | 2016-09-27 | 71.080 mi |
| Registration #20 | 2016-09-27 | 71.080 mi |
| Registration #21 | 2016-09-27 | 71.080 mi |
| Registration #22 | 2016-09-27 | 71.080 mi |
| Registration #23 | 2016-09-27 | 71.080 mi |
| Registration #24 | 2016-09-27 | 71.080 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|--------|---------|
| Width | 2232 mm |
| Height | 1959 mm |
| Length | 4782 mm |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 90 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 3 |
| Engine number | C633409 |