





report date: 2024-03-28

#### General information

Mala	DAMA
Make	BMW
Model	125 225D M SPORT
Colour	Grey
Year of manufacture	2017
Top speed	151 mph
0 - 60 mph	6.2 seconds
Gearbox	8 speed automatic

### Engine & fuel consumption

Power	222 BHP
Max. torque	450 Nm at 1.500 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	121 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

#### Internet history

#### Entry 3

Date	2024-02-25
Distance	

Pictures 0

Listing price <u>View report</u>

#### source: cargurus.co.uk

#### Entry 2

Date	2022-01-18
Pictures	12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-12-14

Pictures 22

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	$\sim$ $-$			
10.71	$\alpha$	- h	sto	rv
101	( ) I		510	II V
	•		-	. ,

MOT expiry date	2025-03-27
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	7
Total items failed	3

MOT #6		2024-03-28 09:28
MOT test	number	669248307568
Result		✓ Passed
Next expiry date 2025-03-27		
Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn on outer edge of tread. (5.2.3 (e))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn on our	ter edge of tread. (5.2.3 (e))

MOT #5	2023-06-08 15:52
MOT test number	402698406115
Result	✓ Passed
MOT #4	2022-06-13 12:43
MOT test number	455486697064
Result	✓ Passed

Result	✓ Passed
MOT #3	2021-11-09 10:03
MOT test number	733938940754
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #1** 2020-11-06 12:15 **MOT** test number 508159444646 Result **X** Failed Offside Rear Road wheel slightly distorted (5.2.2 (c) (i)) **Advice** Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i)) Fail Nearside Front Road wheel badly distorted (5.2.2 (c) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	27 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this BMW? How many owners defined the premium report and see all owner registrations. Download the full report is	
**************************************	
*************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



LD67ZDS report date: 2024-03-28

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-11-16
Last registration	2024-03-28
Complete history	See info



Registration #1	2017-11-16	13 mi
Registration #2	2020-11-06	29.298 mi
Registration #3	2020-11-09	29.298 mi
Registration #4	2021-11-09	37.193 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		T1.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



## Dimensions & weight

Width	1774 mm
Height	1418 mm
Length	4432 mm
Wheel base	2690 mm
Kerb weight	1430 kg
Max. allowed weight	1940 kg

# Additional information

Fuel tank capacity	52 l	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4 page	e 11/11

Number of axles 2

Engine number 52489826