



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA CDTI CLUB
Colour	Blue
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-01
Pictures	25
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #13</b>	2021-09-02 08:57
<b>MOT test number</b>	616326547426
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-09-01
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
<b>Advice</b>	Integral body structure is corroded but structural rigidity is not significantly reduced underbody, suspension components and sub frame corroded (6.1.1 (c) (i))
<b>Advice</b>	Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
<b>Advice</b>	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
<b>Advice</b>	Brake pipe corroded, covered in grease or other material all (1.1.11 (c))
<b>Advice</b>	Front Upper Macpherson strut mounting damaged but not seriously weakened both top mounts (5.3.3 (b) (i))

<b>MOT #12</b>	2020-11-25 16:07
<b>MOT test number</b>	250378836075
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2020-11-25 11:11
<b>MOT test number</b>	587129437158
<b>Result</b>	✗ Failed
<b>Fail</b>	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
<b>Fail</b>	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

<b>MOT #10</b>	2019-05-17 08:36
<b>MOT test number</b>	447356071694
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear tyre slightly perished
<b>Advice</b>	Nearside Rear tyre slightly perished

**MOT #9** 2018-05-18 13:57**MOT test number** 466243558281**Result** ✓ Passed**MOT #8** 2018-05-16 12:14**MOT test number** 748331682565**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #7** 2017-05-17 15:18**MOT test number** 368790731815**Result** ✓ Passed**Advice** Rear tyres slightly perished**MOT #6** 2017-05-17 08:30**MOT test number** 190992670278**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear tyres slightly perished**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-05-26 09:17**MOT test number** 303677946601**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



<b>MOT #4</b>	2015-05-26 09:36
---------------	------------------

<b>MOT test number</b>	297236445183
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2014-05-27 10:51
---------------	------------------

<b>MOT test number</b>	188537544182
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2013-05-28 12:24
---------------	------------------

<b>MOT test number</b>	558188643101
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-05-29 11:34
---------------	------------------

<b>MOT test number</b>	529020052171
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VK09XRM
Plate since	2024-03-29
Current registration	VK09XRM
Plate since	2024-03-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-05-29
Last registration	2021-09-02
Complete history	<a href="#">See info</a>



Registration #1	2009-05-29	10 mi
Registration #2	2012-05-29	16.372 mi
Registration #3	2013-05-28	20.627 mi
Registration #4	2014-05-27	25.109 mi
Registration #5	2015-05-26	29.060 mi
Registration #6	2016-05-26	31.752 mi
Registration #7	2017-05-17	34.203 mi
Registration #8	2017-05-17	34.204 mi
Registration #9	2019-05-29	35.277 mi
Registration #10	2019-05-29	35.277 mi
Registration #11	2019-05-29	35.277 mi
Registration #12	2019-05-29	35.277 mi
Registration #13	2019-05-29	35.277 mi
Registration #14	2019-05-29	35.277 mi
Registration #15	2019-05-29	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1085 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	1144799