





report date: 2024-03-29

General information

Make	FIAT
Model	500X MULTIJET CROSS PLUS
Colour	Red
Year of manufacture	2016
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

 Date
 2021-06-25

 Pictures
 2

Listing price <u>View report</u>





source: cargurus.co.uk

CarCheck.co.uk page 2/11



WO16TYB
report date: 2024-03-29

MOT history

MOT expiry date	2024-07-13
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	7
Total items failed	4

MOT #7	2023-07-07 14:57
MOT test number	757959424369
Result	✓ Passed
Next expiry date	2024-07-13
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #6	2023-07-07 12:14
MOT test number	702494373643
Result	X Failed
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #5	2022-07-14 12:55
MOT test number	127472536678
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-07-14 14:14

MOT test number 893865000986

Result ✓ Passed

MOT #3 2020-06-03 12:17

MOT test number 561070503706

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2020-06-02 08:01

MOT test number 732465670529

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1 2019-06-15 11:53

MOT test number 598331093979

Result \rightarrow Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

$\hat{}$	
()Whor	hictory
OWILL	11151 OT V
Owner	,

For how long did the current and previous owner(s) have this FIAT? How many owners did to Check it in the premium report and see all owner registrations. Download the full report he		e?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	NK NAME OF THE PARTY OF THE PAR	
Plate since		
Current registration	OK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-15
Last registration	2023-07-07
Complete history	See info



Registration #1	2016-06-15	26 mi
Registration #2	2019-06-15	34.087 mi
Registration #3	2020-06-02	45.149 mi
Registration #4	2020-06-03	45.153 mi
Registration #5		11.177 es
Registration #6		11.177 es
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1796 mm
Height	1608 mm
Length	4273 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg

Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 13	1/11

Number of axles 2
Engine number 7704579