



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2009
Top speed	147 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.2 mpg
CO2 emission	188 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-31
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-08
MOT pass rate	100 %
MOT passed	13
Failed MOT tests	0
Total advice items	17
Total items failed	0

MOT #13	2024-03-04 10:19
MOT test number	359206818556
Result	✓ Passed
Next expiry date	2025-03-08
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #12	2023-02-13 10:20
MOT test number	493447639782
Result	✓ Passed
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11	2022-02-16 10:24
MOT test number	898851283613
Result	✓ Passed
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #10	2021-03-04 10:42
MOT test number	355873157677
Result	✓ Passed

**MOT #9** 2020-03-09 12:55**MOT test number** 102810683739**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2019-02-18 11:18**MOT test number** 117243319003**Result** ✓ Passed**Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-02-12 12:56**MOT test number** 729481814664**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2017-02-06 16:03**MOT test number** 114691883580**Result** ✓ Passed**MOT #5** 2016-02-08 16:40**MOT test number** 368915861573**Result** ✓ Passed**Advice** BOTH FRONT TYRES DETERIORATED

**MOT #4** 2015-02-16 11:39**MOT test number** 886507445074**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-02-17 15:20**MOT test number** 116918644451**Result** ✓ Passed**MOT #2** 2013-03-01 13:51**MOT test number** 649790863035**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-02-16 09:23**MOT test number** 887297442094**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
8 March 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-03-01
Last registration	2024-03-04
Complete history	See info



Registration #1	2009-03-01	13 mi
Registration #2	2012-02-16	9.949 mi
Registration #3	2013-03-01	14.226 mi
Registration #4	2014-02-17	19.192 mi
Registration #5	2015-02-16	23.175 mi
Registration #6	2016-02-08	27.984 mi
Registration #7	2017-02-06	32.689 mi
Registration #8	2018-02-12	36.957 mi
Registration #9	2019-03-01	35.000 mi
Registration #10	2020-03-01	35.000 mi
Registration #11	2021-03-01	35.000 mi
Registration #12	2022-03-01	35.000 mi
Registration #13	2023-03-01	35.000 mi
Registration #14	2024-03-01	35.000 mi
Registration #15	2024-03-04	35.000 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1390 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431247491