





report date: 2024-03-28

General information

| Make | VOLVO |
|---------------------|--------------------------------|
| Model | XC60 RDESGN PRO T8 RCHRG AWD A |
| Colour | Blue |
| Year of manufacture | 2020 |
| Top speed | 112 mph |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 385 BHP |
|----------------------|---------------------|
| Max. torque | 400 Nm at 2.200 rpm |
| Engine capacity | 1.969 сс |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption combined | 108.7 mpg |
| CO2 emission | 59 g/km |
| CO2 label | А |



CarCheck.co.uk page 1/10



Internet history

Entry 2

Date 2024-02-09

Pictures 29

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-06-25

Pictures 40

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/10



KR70LWE

report date: 2024-03-28

MOT history

| MOT expiry date | 2024-11-01 |
|--------------------|------------|
| MOT pass rate | 50 % |
| MOT passed | 1 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 2 |

| MOT #2 | | 2023-10-30 14:11 |
|---------------|--|------------------|
| MOT test nu | ımber | 862526740011 |
| Result | | ✓ Passed |
| Next expiry | date | 2024-11-01 |
| Advice | Undertrays/covers fitted to underside and engine | |
| Advice | Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i)) | |

| MOT #1 | 2023-10-27 14:05 | |
|---|------------------|--|
| MOT test number | 788810437532 | |
| Result | × Failed | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | | |
| Advice Offside Front Outer Tyre slightly damaged Outer sidewall damage (5.2.3 (d) (ii)) | | |
| Advice Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i)) | | |
| Advice Undertrays/covers fitted to underside and engine | | |
| Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | | |
| Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Several small cuts in tread and outer sidewall slight damage (5.2.3 (d) (i)) | | |

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 1 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

CarCheck.co.uk page 4/10



KR70LWE

report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



KR70LWE

report date: 2024-03-28

| \sim | | 100 | |
|--------|-----|-----|------|
| Owi | ner | nıs | torv |

| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | |
|--|-------------|
| | |
| | |
| | |
| | |
| THE STATE OF THE S | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 7/10



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2020-11-02 |
| Last registration | 2023-10-30 |
| Complete history | See info |



| Registration #1 | 2020-11-02 | 28 mi |
|-----------------|------------|-----------|
| Registration #2 | | 71.777 es |
| Registration #3 | 2023-10-27 | 36.613 mi |
| Registration #4 | | 77.777 es |
| Registration #5 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

| | | _ | | |
|-------|--------|-------|------|------|
| Dim | ensior | יכ צי | MAIG | ht |
| ווווט | CHOIDE | IS CX | WCIU | IIIL |

| Width | 1999 mm |
|---------------------|---------|
| Height | 1658 mm |
| Length | 4688 mm |
| Wheel base | 2865 mm |
| Kerb weight | 2099 kg |
| Max. allowed weight | 2660 kg |

Additional information

| Fuel tank capacity | 70 I |
|--------------------|---------|
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 3622416 |

CarCheck.co.uk page 10/10