



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Blue
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-08-12
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-08-03
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #21	2020-12-04 13:04
MOT test number	266200998127
Result	✓ Passed
Next expiry date	2021-12-03
Advice	Offside Rear Brake pipe slightly damaged front to rear corroding in clip (1.1.11 (c))

MOT #20	2020-12-03 10:17
MOT test number	257045860797
Result	✗ Failed
Advice	Offside Rear Brake pipe slightly damaged front to rear corroding in clip (1.1.11 (c))
Fail	Offside Front Brake pipe excessively corroded in front arch in yellow chalk (1.1.11 (c))
Fail	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #19	2020-05-11 10:19
MOT test number	667035708785
Result	✗ Failed
Fail	Brake lever has insufficient reserve travel (1.1.2 (a))
Fail	Nearside Front Brake master cylinder/servo mounting prescribed area is excessively corroded and functionality of the braking system is affected (1.1.21 (e) (ii))
Fail	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Oil leak on engine
Advice	Front Exhaust mounting defective down pipe (6.1.2 (a))
Fail	Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt n/s o/s (2.1.3 (g) (ii))



MOT #18

2019-07-18 09:23

MOT test number

230249341271

Result		✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Shock absorbers has a slightly worn bush both bushes. (5.3.2 (c))	
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush. (5.3.4 (a) (i))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Rear Shock absorbers has a slightly worn bush both bushes. (5.3.2 (c))	
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush. (5.3.4 (a) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	

**MOT #17**

2019-07-18 09:23

MOT test number

365073183035

Result**✗ Failed**

- Advice** Nearside Rear Shock absorbers has a slightly worn bush both bushes. (5.3.2 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush. (5.3.4 (a) (i))
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Pass with rectification** Offside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush both bushes. (5.3.2 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush. (5.3.4 (a) (i))
- Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16

2018-07-07 10:45

MOT test number

295783934109

Result**✓ Passed**

- Advice** Both rear brake ferrules slight corroded.
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Parking brake lever, not a lot of reserve travel left.
- Advice** Nearside Front Washer jet doesn't work.
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15**

2017-07-11 15:51

MOT test number

737913405140

Result

✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #14

2017-07-11 13:03

MOT test number

422690699858

Result

✗ Failed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #13** 2016-07-16 09:28**MOT test number** 877798035909**Result** ✓ Passed

- Advice** Engine oil sump corroded but no signs of leaks
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Oil leak engine oil
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #12 2015-07-15 10:42**MOT test number** 899336695109**Result** ✓ Passed**MOT #11** 2014-07-11 09:50**MOT test number** 495592294119**Result** ✓ Passed**MOT #10** 2014-07-09 12:19**MOT test number** 489080394104**Result** ✗ Failed

- Fail** Offside rear brake binding (3.7.B.1)

MOT #9 2013-07-29 10:28**MOT test number** 598640013275**Result** ✓ Passed

**MOT #8** 2013-07-29 10:28**MOT test number** 396840813211**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2012-08-02 14:07**MOT test number** 816255412264**Result** ✓ Passed**MOT #6** 2012-07-31 09:11**MOT test number** 858613112287**Result** ✗ Failed**Notice** Advise engine oil leak**Fail** Offside Rear rear brake binding (3.7.B.1)**MOT #5** 2011-07-01 16:36**MOT test number** 195992281136**Result** ✓ Passed**MOT #4** 2010-07-01 16:55**MOT test number** 280292280449**Result** ✓ Passed**MOT #3** 2009-07-02 16:29**MOT test number** 584583389151**Result** ✓ Passed



MOT #2	2008-07-03 16:07
MOT test number	493545088112
Result	✓ Passed

MOT #1	2008-07-03 12:44
MOT test number	990505788182
Result	✗ Failed

Fail

 Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-06-30
Last registration	2020-12-04
Complete history	See info



Registration #1	2005-06-30	24 mi
Registration #2	2008-07-03	21.114 mi
Registration #3	2008-07-03	21.114 mi
Registration #4	2009-07-02	31.453 mi
Registration #5	2010-07-01	46.047 mi
Registration #6	2011-07-01	58.736 mi
Registration #7	2012-07-31	60.382 mi
Registration #8	2012-08-02	60.382 mi
Registration #9	2013-07-29	63.010 mi
Registration #10	2014-07-09	65.043 mi
Registration #11	2014-07-11	65.051 mi
Registration #12	2015-07-15	66.834 mi
Registration #13	2016-07-15	68.617 mi
Registration #14	2017-07-15	70.400 mi
Registration #15	2018-07-15	72.183 mi
Registration #16	2019-07-15	73.966 mi
Registration #17	2020-07-15	75.749 mi
Registration #18	2021-07-15	77.532 mi
Registration #19	2022-07-15	79.315 mi
Registration #20	2023-07-15	81.098 mi
Registration #21	2024-07-15	82.881 mi
Registration #22	2025-07-15	84.664 mi
Registration #23	2026-07-15	86.447 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FSR95191649