





report date: 2024-03-29

General information

Make	FIAT
Model	500C POP DUALOGIC
Colour	Grey
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-08

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-06
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	14
Total items failed	9

MOT #11		2023-11-07 12:29
MOT test	number	420165434038
Result		✓ Passed
Next expi	ry date	2024-11-06
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

MOT #10	2023-11-07 11:03
MOT test number	314291977827
Result	× Failed
Fail Offside Side repeater not working (4.4.1 (a) (ii))	
Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



LN14XPY

report date: 2024-03-29

MOT #9 2022-11-03 10:06

MOT test number 780389834534

Result ✓ Passed

Advice Front Macpherson strut pin or bush worn but not resulting in excessive movement both sides. (5.3.4 (a) (i))

MOT #8 2022-11-03 10:06

MOT test number 380602655759

Result X Failed

Advice Front Macpherson strut pin or bush worn but not resulting in excessive movement both sides. (5.3.4 (a) (i))

Pass with rectification Front Position lamp not working (4.2.1 (a) (ii))

MOT #7 2021-10-30 15:34

MOT test number 744066610354

Result

Passed

MOT #6 2020-11-02 14:03

MOT test number 954282920830

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



...

MOT #5	2020-11-02 09:50	
MOT test number	790293340476	
Result	× Failed	
Fail Offside Front Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))		
Fail Offside Front Headlamp insecure (4.1.1 (c))		
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3	(d) (i))	
Fail Nearside Front Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))		
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.	3 (d) (i))	
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3	(d) (i))	

MOT #4	2019-10-21 13:45
MOT test number	474348990024
Result	✓ Passed
MOT #3	2019-10-21 09:27
MOT test number	974878053458
Result	★ Failed
Fail Offside Front Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))	
Fail Nearside Front Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))	

Fail Nearside Front Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))		
MOT #2	2018-03-05 12:54	
MOT test number	331731004862	
Result	✓ Passed	
MOT #1	2017-02-20 14:24	
MOT test number	580485954853	
Result	✓ Passed	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	6 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)		·?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	NK NA	
Plate since		
Current registration	NK NA	
Plate since		
	More info	
	More IIII0	

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-07
Last registration	2023-11-07
Complete history	See info



Registration #1	2014-03-07	8 mi
Registration #2	2017-02-20	16.239 mi
Registration #3	2018-03-05	20.227 mi
Registration #4	2019-10-21	22.369 mi
Registration #5	2019-10-21	22.370 mi
Registration #6	2020-11-02	22.933 mi
Registration #7	2020-11-02	22.933 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1340 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number0801996