



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Red
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-26
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-12
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	22
Total items failed	4

MOT #13	2023-12-13 13:32
MOT test number	893509299570
Result	✓ Passed
Next expiry date	2024-12-12
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #12	2022-12-05 09:52
MOT test number	951695310959
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #11**

2022-12-02 10:08

MOT test number

766934302721

Result**✗ Failed**

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #10

2021-11-23 15:57

MOT test number

124495130023

Result**✓ Passed**

Advice Exhaust has a minor leak of exhaust gases backbox (6.1.2 (a))

MOT #9

2021-11-23 11:32

MOT test number

121697724058

Result**✗ Failed**

Advice Exhaust has a minor leak of exhaust gases backbox (6.1.2 (a))

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip broken (6.1.7 (g) (ii))

MOT #8

2020-11-16 17:09

MOT test number

888127456603

Result**✓ Passed**

**MOT #7** 2019-11-20 15:57**MOT test number** 385663469594**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2019-11-20 15:57**MOT test number** 424744358289**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2018-12-12 14:49**MOT test number** 838697320767**Result** ✓ Passed**MOT #4** 2018-05-25 14:13**MOT test number** 455723645562**Result** ✓ Passed**MOT #3** 2017-05-31 12:41**MOT test number** 117909454877**Result** ✓ Passed



MOT #2	2016-05-19 12:24
MOT test number	457267659258
Result	✓ Passed

MOT #1	2015-05-26 15:51
MOT test number	217546445497
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 YH12XAW
Plate since	2019-03-29
Current registration	 YH12XAW
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-28
Last registration	2023-12-13
Complete history	See info



Registration #1	2012-06-28	25 mi
Registration #2	2015-05-26	27.386 mi
Registration #3	2016-05-19	32.456 mi
Registration #4	2017-05-31	36.589 mi
Registration #5	2018-05-25	40.092 mi
Registration #6	2018-12-12	41.851 mi
Registration #7	2019-11-20	50.286 mi
Registration #8	2019-11-20	50.286 mi
Registration #9	2020-05-20	55.277 mi
Registration #10	2020-05-20	55.277 mi
Registration #11	2020-05-20	55.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2020-05-20	55.277 mi
Registration #14	2020-05-20	55.277 mi
Registration #15	2020-05-20	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1097033