



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Blue
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I








Internet history

Entry 1

Date	2021-06-09
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-23
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	57
Total items failed	24

MOT #21	2023-11-24 15:15
MOT test number	847038743181
Result	✓ Passed
Next expiry date	2024-11-23
Advice	Suspension component mounting prescribed area is corroded but not considered excessive general underbody and sills (5.3.6 (a) (i))

MOT #20	2022-11-22 15:24
MOT test number	606175842830
Result	✓ Passed
Advice	Suspension component mounting prescribed area is corroded but not considered excessive both sills (5.3.6 (a) (i))

MOT #19	2021-11-12 15:25
MOT test number	215195487868
Result	✓ Passed
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #18	2020-11-17 13:23
MOT test number	145725058454
Result	✓ Passed
Advice	Low park brake effort
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17**

2020-11-16 12:51

MOT test number

500678889203

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracks in entire tread (5.2.3 (d) (ii))
- Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Exhaust emits black smoke during acceleration (8.2.1.2 (g))
- Advice** Low park brake effort

MOT #16

2019-11-05 14:38

MOT test number

737998276590

Result**✓ Passed**

- Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Tyre worn close to legal limit/worn on edge both front tyres on 3mm of tread 205/55/16 (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Tyre slightly damaged/cracking or perishing both front tyres starting to crack and perish 205/55/16 (5.2.3 (d) (ii))
- Advice** Drivers seat mechanism has play

**MOT #15**

2019-11-05 12:32

MOT test number

984347290624

Result**✗ Failed**

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Tyre worn close to legal limit/worn on edge both front tyres on 3mm of tread 205/55/16 (5.2.3 (e))
- Advice** Drivers seat mechanism has play
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Tyre slightly damaged/cracking or perishing both front tyres starting to crack and perish 205/55/16 (5.2.3 (d) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #14

2018-10-30 15:10

MOT test number

209666605246

Result**✓ Passed**

- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front tyre out of shape 205/55/16
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement suspension arm rear bush (5.3.4 (a) (i))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement suspension arm rear bush (5.3.4 (a) (i))
- Advice** Nearside Front rim dented

**MOT #13**

2018-10-30 09:57

MOT test number

340133189909

Result**✗ Failed**

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure 205/55/16 (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement suspension arm rear bush (5.3.4 (a) (i))

Advice Nearside Front tyre out of shape 205/55/16

Fail Emissions not tested due to EML light on (8.2.1.2 (d))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement suspension arm rear bush (5.3.4 (a) (i))

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure 205/55/16 (5.2.3 (d) (ii))

Advice Nearside Front rim dented

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #12

2017-10-04 15:38

MOT test number

490945592786

Result**✓ Passed**

Advice Rear Child Seat fitted not allowing full inspection of adult belt x 2



MOT #11	2017-10-04 13:05
MOT test number	281201121248
Result	✗ Failed
Fail	Electronic stability system warning lamp indicates a fault (3.4.1c)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
Advice	Rear Child Seat fitted not allowing full inspection of adult belt x 2

MOT #10	2016-09-15 09:46
MOT test number	960899228953
Result	✓ Passed
Advice	Offside Front disc heavily scored
Advice	EML light on
Advice	Front discs have a lip on there outer edge
Advice	Child Seat fitted not allowing full inspection of adult belt both rear seats
Advice	Traction control light on

**MOT #9**

2016-09-14 16:36

MOT test number

463464072598

Result**✗ Failed**

- Advice** Child Seat fitted not allowing full inspection of adult belt both rear seats
- Advice** EML light on
- Advice** Front discs have a lip on there outer edge
- Fail** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp position to hazards (1.1.A.3f)
- Fail** Offside Front Tyre has ply or cords exposed 205/55/16 (4.1.D.1b)
- Advice** Traction control light on
- Advice** Offside Front disc heavily scored
- Fail** Nearside Front Tyre has ply or cords exposed 205/55/16 (4.1.D.1b)

MOT #8

2015-09-09 11:31

MOT test number

236866680737

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7

2014-09-04 14:37

MOT test number

349667244478

Result**✓ Passed**

- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #6** 2013-09-18 08:51**MOT test number** 285811663226**Result** ✓ Passed**MOT #5** 2012-05-09 11:36**MOT test number** 466430432163**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-05-09 11:36**MOT test number** 279450832460**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-05-11 11:48**MOT test number** 806601231180**Result** ✓ Passed**MOT #2** 2010-05-12 11:45**MOT test number** 710222830119**Result** ✓ Passed



MOT #1	2010-05-12 11:45
MOT test number	340102930130
Result	✗ Failed
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 November 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	23 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-05-10
Last registration	2023-11-24
Complete history	See info



Registration #1	2007-05-10	26 mi
Registration #2	2010-05-12	25.158 mi
Registration #3	2010-05-12	15.158 mi
Registration #4	2011-05-11	34.335 mi
Registration #5	2012-05-09	40.663 mi
Registration #6	2013-09-18	47.535 mi
Registration #7	2014-09-04	51.984 mi
Registration #8	2015-09-09	57.083 mi
Registration #9	2016-09-14	63.797 mi
Registration #10	2016-09-15	63.797 mi
Registration #11	2017-10-04	70.539 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi
Registration #21	2019-05-29	75.277 mi
Registration #22	2019-05-29	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 056261