



UK

GLI4YAH

report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 DSTYLE
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 2



Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

Entry 1

Date	2021-01-21
Pictures	50
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2025-03-12
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	1

## MOT #10 2024-03-13 12:14

MOT test number 630530114317

Result ✓ Passed

Next expiry date 2025-03-12

- Advice** Rear Service brake binding but not excessively both (1.2.1 (f))
- Advice** Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing walls cracking (5.2.3 (d) (ii))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

## MOT #9 2023-02-28 11:35

MOT test number 689693050459

Result ✓ Passed

- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both + osr showing signs of heat (1.1.14 (a) (ii))

**MOT #8** 2023-02-27 14:15**MOT test number** 719958951013**Result** ✗ Failed**MAJOR** Front Windscreen washer not working (3.5 (a))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both + osr showing signs of heat (1.1.14 (a) (ii))**MOT #7** 2022-03-03 10:56**MOT test number** 445963321920**Result** ✓ Passed**MOT #6** 2021-01-30 11:13**MOT test number** 684309282554**Result** ✓ Passed**MOT #5** 2019-12-31 10:47**MOT test number** 734347108593**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin on/close minimum where visible (1.1.13 (a) (ii))**Advice** Rear Exhaust mounting defective bracket broken off pipe (6.1.2 (a))**Advice** Front Brake disc worn, but not excessively heavy lipping (1.1.14 (a) (i))**MOT #4** 2018-12-28 10:46**MOT test number** 660348015537**Result** ✓ Passed**Advice** Centre/rear exhaust mounting corroding



MOT #3	2017-12-19 11:26
MOT test number	425498361721
Result	✓ Passed
MOT #2	2017-01-03 12:29
MOT test number	969325262453
Result	✓ Passed
MOT #1	2017-01-03 12:29
MOT test number	270327923005
Result	✗ Failed
<div>Pass with rectification</div> Offside Headlamp aim too high (1.8)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
12 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	12 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-30
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2014-05-30	21 mi
Registration #2	2017-01-03	7.821 mi
Registration #3	2017-01-03	7.821 mi
Registration #4	2017-12-19	16.284 mi
Registration #5	2018-12-28	24.136 mi
Registration #6	2019-12-31	32.531 mi
Registration #7	2020-03-28	35.277 mi
Registration #8	2020-03-28	35.277 mi
Registration #9	2020-03-28	35.277 mi
Registration #10	2020-03-28	35.277 mi
Registration #11	2020-03-28	35.277 mi
Registration #12	2020-03-28	35.277 mi
Registration #13	2020-03-28	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1075 kg
Max. allowed weight	1554 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA2082498