



LE06HWK

report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH D 815 ENTERPRISE P/V
Colour	White
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	71 BHP
Max. torque	125 Nm at 2.500 rpm
Engine capacity	1.868 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-16
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-04
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	53
Total items failed	8

MOT #19 2024-01-03 10:52

MOT test number 414631858291

Result ✓ Passed

Next expiry date 2025-01-04

Advice O/s/f inner arch liner loose

Minor Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Corrosion to n/s & o/s/r box section behind rear bumper

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18 2023-01-05 12:30

MOT test number 372315548646

Result ✓ Passed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

Advice N/s/r and O/s/r box section (behind bumper) corroded

Advice O/s/f arch liner catching on driveshaft

Advice N/s headlight in poor condition

**MOT #17**

2023-01-04 15:15

MOT test number

362605894245

Result

✗ Failed

Fail Nearside Headlamp aim too low (4.1.2 (a))**Advice** N/s/r and O/s/r box section (behind bumper) corroded**Fail** Nearside Headlamp insecure (4.1.1 (c))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** O/s/f arch liner catching on driveshaft**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))**MOT #16**

2021-12-21 12:17

MOT test number

623671961632

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**MOT #15**

2020-12-14 08:23

MOT test number

564377012526

Result

✓ Passed

MOT #14

2019-07-03 07:10

MOT test number

690849748986

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13**

2018-06-14 08:58

MOT test number

113504554741

Result

✓ Passed

**MOT #12**

2017-05-26 16:07

MOT test number

209376791565

Result

✓ Passed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Play in steering rack inner joint(s)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #11

2017-05-26 11:22

MOT test number

303990515823

Result

✗ Failed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

Advice Play in steering rack inner joint(s)

Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #10

2016-05-21 10:40

MOT test number

111313670678

Result

✓ Passed

Advice Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #9** 2016-05-20 14:02**MOT test number** 770841649679**Result** ✗ Failed

Advice Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Fail Exhaust has a major leak of exhaust gases (7.1.2)

MOT #8 2015-06-10 09:30**MOT test number** 987301265139**Result** ✓ Passed

Advice Steering system has slight free play detected at steering wheel (2.2.A.1b)

Advice Offside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Notice Oil leak

Advice Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #7 2014-06-06 08:54**MOT test number** 369027054110**Result** ✓ Passed

Advice Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Notice Nearside front tyre wearing on outer edge

Notice Wipers split but still clearing screen

Notice Play in steering rack inner joint(s)

**MOT #6** 2013-06-03 09:46**MOT test number** 677264353157**Result** ✓ Passed**Notice** Exhaust deteriorated**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #5** 2013-06-03 09:46**MOT test number** 695214053171**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Exhaust deteriorated**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #4** 2012-05-25 13:55**MOT test number** 819916342157**Result** ✓ Passed**Notice** O/s/f tyre tread on 1.6mm**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** N/s/f tyre tread on 1.6mm**Notice** Oil leak

**MOT #3** 2011-06-03 11:44**MOT test number** 426634951198**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Notice** O/s door mirror casing broken**MOT #2** 2010-06-01 16:28**MOT test number** 331412950196**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Advice** Nearside Rear Road wheel slightly damaged (4.2.A.1a)**MOT #1** 2009-06-18 12:00**MOT test number** 581599569139**Result** ✓ Passed**Advice** Offside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
4 January 2025

Tax status	Valid until 1 January
-------------------	-----------------------

Days left	247
------------------	-----

MOT expiry date	4 January 2025
------------------------	----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-08-17
Last registration	2024-01-03
Complete history	See info



Registration #1	2006-08-17	16 mi
Registration #2	2009-06-18	28.976 mi
Registration #3	2010-06-01	42.937 mi
Registration #4	2011-06-03	49.938 mi
Registration #5	2012-05-25	57.043 mi
Registration #6	2013-06-03	63.935 mi
Registration #7	2014-06-06	70.976 mi
Registration #8	2015-06-10	77.357 mi
Registration #9	2016-05-20	83.144 mi
Registration #10	2016-05-21	83.144 mi
Registration #11	2016-05-21	83.144 mi
Registration #12	2016-05-21	83.144 mi
Registration #13	2016-05-21	83.144 mi
Registration #14	2016-05-21	83.144 mi
Registration #15	2016-05-21	83.144 mi
Registration #16	2016-05-21	83.144 mi
Registration #17	2016-05-21	83.144 mi
Registration #18	2016-05-21	83.144 mi
Registration #19	2016-05-21	83.144 mi
Registration #20	2016-05-21	83.144 mi

More info >



Dimensions & weight

Width	2134 mm
Height	1940 mm
Length	4522 mm
Kerb weight	1390 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Indirect Injection
Number of doors	5
Number of seats	3
Engine number	DXFP6050943