



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI DSG 140
Colour	Black
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	172 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-07-21
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	27
Total items failed	8

MOT #16	2023-07-28 11:27
---------	------------------

MOT test number	330475039077
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-27
------------------	------------

- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Manufactures under trays fitted restricting inspection of components (brake pipes
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15**

2022-07-13 10:48

MOT test number

594340210916

Result

✓ Passed

- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Manufactures under trays fitted restricting inspection of components (brake pipes)
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14

2021-04-20 15:06

MOT test number

768793800431

Result

✓ Passed

- Advice** Under guards fitted to front,centre and rear of car

MOT #13

2021-04-07 10:41

MOT test number

267191463256

Result

✗ Failed

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Under guards fitted to front,centre and rear of car
- Fail** Nearside Side repeater not working in mirror (4.4.1 (a) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12** 2020-02-26 09:28**MOT test number** 216176458633**Result** ✓ Passed**MOT #11** 2019-02-19 10:13**MOT test number** 522296455581**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2018-02-16 10:02**MOT test number** 452600335190**Result** ✓ Passed**Advice** N/S/R seat belt plastic cover missing**MOT #9** 2017-02-16 11:30**MOT test number** 632619881565**Result** ✓ Passed**Advice** Nearside Rear Tyre starting to perish**Advice** Offside Rear Tyre starting to perish**MOT #8** 2016-02-16 11:54**MOT test number** 139401637857**Result** ✓ Passed

**MOT #7** 2016-02-16 11:54**MOT test number** 284894380406**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2015-03-05 16:46**MOT test number** 579604065088**Result** ✓ Passed**MOT #5** 2014-08-08 14:36**MOT test number** 106020424214**Result** ✓ Passed**Advice** Inner Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-08-07 13:07**MOT test number** 196809714221**Result** ✗ Failed**Advice** Inner Front Brake pad(s) wearing thin (3.5.1g)**Notice** Near side wing mirror incomplete but functional.**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2013-07-17 15:32**MOT test number** 359788993193**Result** ✓ Passed



MOT #2	2013-07-17 15:32
MOT test number	329858093115
Result	✗ Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)

MOT #1	2012-11-19 10:33
MOT test number	617224222383
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LC59YHD
Plate since	2024-03-29
Current registration	 LC59YHD
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-11-25
Last registration	2023-07-28
Complete history	See info



Registration #1	2009-11-25	18 mi
Registration #2	2012-11-19	39.213 mi
Registration #3	2013-07-17	42.467 mi
Registration #4	2014-08-07	61.318 mi
Registration #5	2014-08-08	61.319 mi
Registration #6	2015-03-05	70.700 mi
Registration #7	2016-02-16	74.584 mi
Registration #8	2016-02-16	74.584 mi
Registration #9	2017-02-16	78.479 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2019-05-29	95.277 mi
Registration #13	2019-05-29	95.277 mi
Registration #14	2019-05-29	95.277 mi
Registration #15	2019-05-29	95.277 mi
Registration #16	2019-05-29	95.277 mi
Registration #17	2019-05-29	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

BKD C66894