





General information

| Make | KIA |
|---------------------|----------------|
| Model | RIO CRDI S |
| Colour | Black |
| Year of manufacture | 2007 |
| Top speed | 109 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 109 BHP |
|-------------------------|---------------------|
| Max. torque | 235 Nm at 1.900 rpm |
| Engine capacity | 1.493 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 121 g/km |
| CO2 label | D |





MOT history

| MOT expiry date | 2020-09-07 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 30 |
| Total items failed | 4 |

| MOT #15 | 2019-09-06 07:44 |
|--|---|
| MOT test number | 986472874591 |
| Result | ✓ Passed |
| Next expiry date | 2020-09-07 |
| Minor Offside Registration plate lamp inoperative in the case (i)) | e of multiple lamps or light sources (4.7.1 (b) |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice Offside Track rod end ball joint has slight play (2.1.3) | (b) (i)) |
| Minor Nearside Suspension arm ball joint dust cover severely | y deteriorated (5.3.4 (b) (i)) |
| Advice Nearside Suspension arm ball joint has slight play (5.) | 3.4 (a) (i)) |

| MOT #14 | 2019-09-06 07:44 |
|--|--------------------|
| MOT test number | 253066599315 |
| Result | 🗙 Failed |
| Pass with rectification contacted (6.1.4 (a) (i)) Nearside Rear Bumper damaged and likely to cause injury wh | en grazed or |
| Minor Nearside Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i) |) |
| Advice Nearside Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |
| Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light (i)) | sources (4.7.1 (b) |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |





| MOT #13 | 20 | 18-09-07 16:13 |
|----------|--|----------------|
| MOT test | number | 434611650613 |
| Result | | ✓ Passed |
| Advice | Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |
| Advice | Items removed from driver's view prior to test | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e)) | |
| Advice | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Advice | Child Seat fitted not allowing full inspection of adult belt both rear and nearside from | ıt |

| MOT #12 | | 2018-09-06 10:19 |
|----------------|---|-------------------------|
| MOT test i | number | 235655930226 |
| Result | | 🗙 Failed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 | (e)) |
| MAJOR (ii)) | Offside Rear Registration plate lamp inoperative in the case of a single lamp of | or all lamps (4.7.1 (b) |
| Advice | Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |
| Advice | Items removed from driver's view prior to test | |
| Advice | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Advice | Child Seat fitted not allowing full inspection of adult belt both rear and nearsion | de front |

| MOT #11 | 2017-09-06 10:47 |
|-----------------|------------------|
| MOT test number | 122759466444 |
| Result | ✓ Passed |





| MOT #10 | | 2016-09-08 16:20 |
|----------|---|------------------|
| MOT test | number | 939419172283 |
| Result | | 🗸 Passed |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i) | |
| Advice | Both rear tyres perished | |

| МОТ #9 | 2016-09-08 16:20 |
|--|---|
| MOT test number | 687763074361 |
| Result | × Failed |
| Pass with rectification | Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i) | |
| Advice Both rear tyres p | perished |

| MOT #8 | 2015-09-04 08:46 |
|----------------------------------|------------------|
| MOT test number | 203063213390 |
| Result | ✓ Passed |
| Advice Both Rear Tyres Perished. | |

| MOT #7 | 20 | 14-07-09 09:38 |
|----------|--|----------------|
| MOT test | number | 338510594196 |
| Result | | ✓ Passed |
| Notice | Both rear tyres deteriorated | |
| Advice | Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| Notice | Osr brake slight binding | |
| Advice | Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |





| MOT #6 | 2013-07-04 13:19 |
|---|------------------|
| MOT test number | 127205883154 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2012-09-18 15:53 |
| MOT test number | 288152862284 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2011-09-28 12:25 |
| MOT test number | 429981371237 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2010-11-01 14:08 |
| MOT test number | 241755000307 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2010-09-01 16:30 |
| MOT test number | 100074840204 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2010-09-01 11:52 |
| MOT test number | 460974940287 |
| Result | 🗙 Failed |
| | |
| FailNearside Front Tyre has ply or cords exposed (4.1.D.1b) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |



Tax & MOT check

| X Untaxed Tax expired: 18 November 2019 | X MOT Expired: 7 September 2020 |
|--|---|
| Tax status | Expired at 18 November 2019 |
| Days left | 1623 days too late |
| MOT expiry date | 7 September 2020 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FE CO |
| Category | Lashe |
| Туре | |
| Damage 2 | AMPLE |
| Damaye 2 | e e et al |
| Date | 1. |
| Category | AMP |
| Туре | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******** | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | 7 |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2007-09-03 |
| Last registration | 2019-09-06 |
| Complete history | See info |



| Registration #1 | 2007-09-03 | 20 mi |
|-------------------|------------|------------|
| Registration #2 | 2010-09-01 | 34.718 mi |
| Registration #3 | 2010-09-01 | 34.718 mi |
| Registration #4 | 2010-11-01 | 36.337 mi |
| Registration #5 | 2011-09-28 | 43.819 mi |
| Registration #6 | 2012-09-18 | 50.867 mi |
| Registration #7 | 2013-07-04 | 54.090 mi |
| Registration #8 | 2014-07-09 | 58.128 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 esi |
| Deviaturation #15 | | |
| Registration #15 | | 11.777 est |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1695 mm |
| Height | 1470 mm |
| Length | 3990 mm |
| Wheel base | 2500 mm |
| Kerb weight | 1146 kg |
| Max. allowed weight | 1650 kg |
| Additional information | |
| Fuel tank capacity | 45 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | D4FA6H33039 |