





### General information

| Make                | MAZDA          |
|---------------------|----------------|
| Model               | 6 D SPORT NAV  |
| Colour              | Red            |
| Year of manufacture | 2016           |
| Top speed           | 131 mph        |
| 0 - 60 mph          | 9.1 seconds    |
| Gearbox             | 6 speed Manual |

### Engine & fuel consumption

| Power                   | 148 BHP             |
|-------------------------|---------------------|
| Max. torque             | 380 Nm at 2.600 rpm |
| Engine capacity         | 2.191 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 60.1 mpg            |
| Consumption extra urban | 83.1 mpg            |
| Consumption combined    | 72.4 mpg            |
| CO2 emission            | 107 g/km            |
| CO2 label               | В                   |







| Internet history |             |
|------------------|-------------|
| Entry 1          |             |
| Date             | 2021-07-16  |
| Pictures         | 0           |
| Listing price    | View report |

source: cargurus.co.uk



### MOT history

| MOT expiry date    | 2025-01-05 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 6          |
| Failed MOT tests   | 0          |
| Total advice items | 6          |
| Total items failed | 0          |

| MOT #6           | 2023-12-19 16:07 |
|------------------|------------------|
| MOT test number  | 297138540294     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-01-05       |

| MOT #5          | 2023-01-06 12:03 |
|-----------------|------------------|
| MOT test number | 258076609290     |
| Result          | ✓ Passed         |

| MOT #4   |  | 2022-08-20 11:54 |
|----------|--|------------------|
| MOT test | number   | 663193143912     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Rear Nail in tyre  |                  |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |
| Advice   | Nearside Rear Nail in tyre   |                  |

| MOT #3          | 2021-08-09 15:13 |
|-----------------|------------------|
| MOT test number | 175467315355     |
| Result          | ✓ Passed         |





| MOT #2   |  | 2020-07-22 09:03 |
|----------|--|------------------|
| MOT test | number   | 951858183446     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
| Advice   | Offside Rear Nail in tyre  |                  |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
|          |  |                  |
| MOT #1   |  | 2019-07-22 10:51 |

|                 | 2019-07-22 10.51 |
|-----------------|------------------|
| MOT test number | 727816765566     |
| Result          | ✓ Passed         |





Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 January 2025 | ✓<br>MOT<br>Expires:<br>5 January 2025 |
|--|--|
| Tax status                               | Valid until 1 January                  |
| Days left                                | 248                                    |
| MOT expiry date                          | 5 January 2025                         |
| Full MOT history                         | See MOT history                        |
| Tax calculation                          |  |

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | В              |
| Single payment (12 months)              | £ 20,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,-      |





#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |           |
|----------|-----------|
| Date     | FEIDO     |
| Category | 4. ALANPE |
| Туре     |           |
| Damage 2 | AMPL      |
|          | F Store   |
| Date     | 1. E      |
| Category | ame       |
| Туре     |           |

#### Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 =      |





## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| NUMBER OF TAXABLE PARTY |             |
|--|-------------|
| **********   |             |
| ********   |             |
| *******  |             |
| ***********  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this MAZDA had different number plates.   |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Carrent registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 8          |
| First mileage registration | 2016-08-04 |
| Last registration          | 2023-12-19 |
| Complete history           | See info   |



| Registration #1 | 2016-08-04 | 29 mi      |
|-----------------|------------|------------|
| Registration #2 | 2019-07-22 | 34.352 mi  |
| Registration #3 | 2020-07-22 | 43.671 mi  |
| Registration #4 |            | 11.777 esi |
| Registration #5 |            | 11.777 mi  |
| Registration #6 |            | 11.777 esi |
| Registration #7 |            | 11.777 mi  |
| Registration #8 |            | T1.777 esi |





# Safety ratings

| NCAP rating    | ****                   |
|----------------|------------------------|
| Adult          | 92%                    |
| Children       | 77%                    |
| Pedestrian     | 66%                    |
| Safety systems | 81%                    |
| Overall rating | 83%                    |
| Video          | <u>see crash video</u> |



| Dimensions & weight                                    |                          |
|--|--------------------------|
| Width  | 1840 mm                  |
| Height   | 1450 mm                  |
| Length   | 4865 mm                  |
| Wheel base   | 2830 mm                  |
| Kerb weight  | 1405 kg                  |
| Max. allowed weight                                    | 2055 kg                  |
|  |                          |
| Additional information                                 |                          |
| Additional information Fuel tank capacity              | 62 l                     |
|  | 62 l<br>Direct Injection |
| Fuel tank capacity                                     |                          |
| Fuel tank capacity<br>Fuel delivery                    | Direct Injection         |
| Fuel tank capacity<br>Fuel delivery<br>Number of doors | Direct Injection<br>4    |