

Ford



# General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	68 BHP	
Max. torque	102 Nm at 3.000 rpm	
Engine capacity	1.242 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	44.8 mpg	
Consumption extra urban	64.2 mpg	
Consumption combined	55.4 mpg	
CO2 emission	119 g/km	
CO2 label	С	





# MOT history

MOT expiry date	2024-03-24
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	31
Total items failed	5

MOT #16	2023-03-22 18:15
MOT test number	574541628846
Result	✓ Passed
Next expiry date	2024-03-24

MOT #15	202	23-03-21 09:48
MOT test	number	47928525693
Result		🗙 Failed
MAJOR	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))	
MAJOR	Nearside Rear Coil spring mounting corroded and seriously weakened (5.3.1 (b) (i))	

MOT #14	2022-03-15 17:50
MOT test number	570776640356
Result	✓ Passed
MOT #13	2021-03-25 13:02
MOT test number	546070962276

Result

MOT #12	2020-02-26 16:32
MOT test number	489262576399
Result	✓ Passed

🗸 Passed





MOT #11		2020-02-25 16:09
MOT test	number	729736918679
Result		🗙 Failed
DANGER	<b>OUS</b> Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)	)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
MAJOR	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	
Advice	Rear axle slightly corroded	
MAJOR	Offside Rear Parking brake inoperative on one side (1.4.1 (a))	

MOT #10		2019-04-25 12:39
MOT test	number	202236262621
Result		✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping eff	ect (5.3.2 (b))

MOT #9		2018-05-30 09:53
MOT test	number	733643816955
Result		✓ Passed
Advice	Exhaust silencer slightly loose corroded (8.1.1 (b) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))	
Advice	Nearside Front clutch pipe insecure	





MOT #8		2018-05-28 13:01
MOT test	number	684274294215
Result		🗙 Failed
MAJOR	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b	) (ii))
Advice	Exhaust silencer slightly loose corroded (8.1.1 (b) (i))	
DANGER	<b>OUS</b> Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	)
MAJOR	Offside Rear Parking brake inoperative on one side (1.4.1 (a))	
Advice	Nearside Front clutch pipe insecure	
MAJOR	Offside Front Position lamp not working (4.2.1 (a))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	

MOT #7		2017-05-31 09:06
MOT test	number	505911673544
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin inner pad advise replacement asa	p (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit wearing inner edge (4.1.E	E.1)
<b>Advice</b> (3.5.1i)	Front brake disc worn, pitted or scored, but not seriously weakened both s	sides in poor condition
Advice	Outer skin rear silencer corroded	



SG10VSC report date: 2024-03-28

MOT #6	2017-05-30 12:46
MOT test number	434906995805
Result	🗙 Failed
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Advice Offside Front Brake pad(s) wearing thin inner pad advise replacement asap (3.5	.1g)
Advice Outer skin rear silencer corroded	
Advice Nearside Front Tyre worn close to the legal limit wearing inner edge (4.1.E.1)	
<b>Fail</b> Offside Rear rear parking brake recording little or no effort (3.7.B.6a)	
Fail Nearside Front Direction indicator not working (1.4.A.2c)	
Advice (3.5.1i) Front brake disc worn, pitted or scored, but not seriously weakened both sides i	n poor condition
Fail Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)	

MOT #5	2016-05-06 11:29
MOT test number	948356735837
Result	✓ Passed

MOT #4	2015-05-05 11:06
MOT test number	668045425143
Result	✓ Passed

MOT #3		2015-05-05 11:06
MOT test number		325765425197
Result		🗙 Failed
Pass with rectification	Nearside Front Windscreen wiper blade insecure (8.2.2)	

MOT #2	2014-04-17 11:16
MOT test number	176857404172
Result	✓ Passed





MOT #1	2013-04-20 10:22
MOT test number	237240713137
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	<b>X</b> <b>MOT</b> Expired: 24 March 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	24 March 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-05-08
Last registration	2023-03-22
Complete history	See info



Registration #1	2010-05-08	15 mi
Registration #2	2013-04-20	8.984 mi
Registration #3	2014-04-17	16.759 mi
Registration #4	2015-05-05	23.819 mi
Registration #5	2016-05-06	30.710 mi
Registration #6	2017-05-30	35.815 mi
Registration #7	2017-05-31	35.817 mi
Registration #8	2018-05-28	45.656 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi





### Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	5775203