



report date: 2024-03-28

General information

Make	KIA
Model	CEED CRDI 3 ISG
Colour	White
Year of manufacture	2018
Top speed	119 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	76.3 mpg
Consumption combined	58.9 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-27
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-10-08
<b>MOT pass rate</b>	75 %
<b>MOT passed</b>	3
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	11
<b>Total items failed</b>	2

**MOT #4** 2023-10-09 15:01**MOT test number** 161245307465**Result** Passed**Next expiry date** 2024-10-08

- Advice** Front bumper damaged
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #3** 2022-10-04 15:26**MOT test number** 157605626431**Result** Passed

- Advice** Nearside Lower front bumper damaged

**MOT #2** 2022-10-03 16:11**MOT test number** 324740553795**Result** ✗ Failed**Advice** Offside Lower front bumper damaged**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure tyre distorted/warped (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure tyre distorted/warped (5.2.3 (d) (ii))**MOT #1** 2021-07-27 14:00**MOT test number** 901051054553**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
8 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	8 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>First licence fee (12 months)</b>	£ 185,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-08-22
Last registration	2023-10-09
Complete history	<a href="#">See info</a>



Registration #1	2018-08-22	27 mi
Registration #2	2021-07-27	22.878 mi
Registration #3	2023-10-09	25.277 mi
Registration #4	2023-10-09	25.277 mi
Registration #5	2023-10-09	25.277 mi
Registration #6	2023-10-09	25.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1800 mm
Height	1447 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1388 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FEJZ018820