



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | MAZDA |
| Model | MX-5 I |
| Colour | Silver |
| Year of manufacture | 2003 |
| Top speed | 127 mph |
| 0 - 60 mph | 8.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 138 BHP |
| Max. torque | 162 Nm at 4.500 rpm |
| Engine capacity | 1.840 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 25.0 mpg |
| Consumption extra urban | 40.4 mpg |
| Consumption combined | 32.8 mpg |
| CO2 emission | 210 g/km |
| CO2 label | K |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-20 |
| Pictures | 10 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2022-04-14 |
| MOT pass rate | 72 % |
| MOT passed | 13 |
| Failed MOT tests | 5 |
| Total advice items | 14 |
| Total items failed | 17 |

MOT #18 2021-04-15 11:00

MOT test number 433704974940

Result ✓ Passed

Next expiry date 2022-04-14

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Both outer sills repaired and undersealed

Minor Offside Rear Battery insecure but not likely to fall from carrier boot floor corroded and hole (4.13 (a) (i))

MOT #17 2021-04-12 08:44

MOT test number 941011647131

Result ✗ Failed

Minor Offside Rear Battery insecure but not likely to fall from carrier boot floor corroded and hole (4.13 (a) (i))

Advice Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))

Fail Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))

Advice Both outer sills repaired and undersealed

**MOT #16** 2019-04-29 13:32**MOT test number** 637513286638**Result** ✓ Passed**Advice** Offside Rear outer sill corroded**Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**Advice** Nearside Rear outer sill corroded**MOT #15** 2017-04-28 12:50**MOT test number** 576675582665**Result** ✓ Passed**MOT #14** 2016-04-15 11:43**MOT test number** 655839266532**Result** ✓ Passed**Advice** Offside Front position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)**MOT #13** 2015-04-21 08:47**MOT test number** 189711415122**Result** ✓ Passed**MOT #12** 2014-04-29 18:21**MOT test number** 246709314121**Result** ✓ Passed**MOT #11** 2013-02-28 14:03**MOT test number** 507069653012**Result** ✓ Passed

**MOT #10** 2011-09-24 09:48**MOT test number** 745337961254**Result** ✓ Passed**MOT #9** 2011-03-16 18:10**MOT test number** 149255771485**Result** ✓ Passed**MOT #8** 2011-03-15 13:02**MOT test number** 157044271412**Result** ✗ Failed

- Fail** Offside Headlamp aim too far to the right (1.8)
- Fail** Nearside rear brake binding (3.7.B.1)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Rear brake application uneven (3.7.B.2)

MOT #7 2010-03-17 12:15**MOT test number** 704036670098**Result** ✓ Passed

- Notice** Parking brake travel near to limit

MOT #6 2010-03-17 12:15**MOT test number** 183056170003**Result** ✗ Failed

- Pass with rectification** Nearside Front Headlamp aim too high (1.8)
- Pass with rectification** Nearside Front Headlamp aim too high and too far to the left. (1.8)
- Notice** Parking brake travel near to limit

**MOT #5** 2009-03-19 14:31**MOT test number** 422168379097**Result** ✓ Passed**MOT #4** 2009-03-17 09:55**MOT test number** 810806179040**Result** ✗ Failed

- Fail** Offside Rear brake disc excessively pitted (3.5.1h)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front brake disc excessively pitted (3.5.1h)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2007-06-07 12:23**MOT test number** 450208157172**Result** ✓ Passed**MOT #2** 2007-06-06 10:24**MOT test number** 813667957114**Result** ✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1 2006-06-01 17:14**MOT test number** 193272756172**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 June 2022

X

MOT

Expired:
14 April 2022

| | |
|------------------|---------------------------------|
| Tax status | Expired at 1 June 2022 |
| Days left | 699 days too late |
| MOT expiry date | 14 April 2022 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | YF03K GK |
| Plate since | 2019-03-28 |
| Current registration | YF03K GK |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2003-05-21 |
| Last registration | 2021-04-15 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2003-05-21 | 8 mi |
| Registration #2 | 2006-06-01 | 48.295 mi |
| Registration #3 | 2007-06-06 | 71.166 mi |
| Registration #4 | 2007-06-07 | 71.166 mi |
| Registration #5 | 2009-03-17 | 77.302 mi |
| Registration #6 | 2009-03-19 | 77.302 mi |
| Registration #7 | 2010-03-17 | 80.225 mi |
| Registration #8 | 2011-03-15 | 84.735 mi |
| Registration #9 | 2011-03-16 | 84.735 mi |
| Registration #10 | 2011-09-24 | 86.443 mi |
| Registration #11 | 2012-03-20 | 86.443 mi |
| Registration #12 | 2012-03-20 | 86.443 mi |
| Registration #13 | 2012-03-20 | 86.443 mi |
| Registration #14 | 2012-03-20 | 86.443 mi |
| Registration #15 | 2012-03-20 | 86.443 mi |
| Registration #16 | 2012-03-20 | 86.443 mi |
| Registration #17 | 2012-03-20 | 86.443 mi |
| Registration #18 | 2012-03-20 | 86.443 mi |
| Registration #19 | 2012-03-20 | 86.443 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|-------------|---------|
| Width | 1680 mm |
| Height | 1225 mm |
| Length | 3975 mm |
| Wheel base | 2265 mm |
| Kerb weight | 1065 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of axles | 2 |
| Engine number | BP 538310 |