



General information

Make	VOLKSWAGEN
Model	PASSAT R LINE TDI
Colour	Black
Year of manufacture	2010
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-24
Pictures	9
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-03
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	25
Total items failed	12

MOT #14	2024-02-28 16:35
MOT test number	860685361119
Result	✓ Passed
Next expiry date	2025-03-03

MOT #13	2024-02-28 14:44
MOT test number	149242989462
Result	✗ Failed
Fail	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #12	2023-03-04 16:16
MOT test number	204229588943
Result	✓ Passed

**MOT #11**

2023-03-03 11:30

MOT test number

256942945705

Result**✗ Failed**

- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm 235/45/17 (5.2.3 (e))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure 235/45/17 (5.2.3 (d) (ii))

MOT #10

2022-02-28 11:34

MOT test number

931756072534

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9

2021-02-05 11:11

MOT test number

688802617859

Result**✓ Passed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #8** 2019-07-25 14:07**MOT test number** 371267996015**Result** ✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2018-04-16 13:14**MOT test number** 585893846354**Result** ✓ Passed

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Front Tyre slightly damaged on sidewall not showing cords

MOT #6 2017-04-21 10:35**MOT test number** 967454855047**Result** ✓ Passed

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT #5 2016-04-05 12:11**MOT test number** 494118042652**Result** ✓ Passed

**MOT #4** 2016-04-04 14:55**MOT test number** 632448986082**Result** ✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Side repeater not working (1.4.A.2c)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2015-06-24 11:32**MOT test number** 565335375181**Result** ✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Rear tyres wearing uneven

MOT #2 2014-06-23 10:29**MOT test number** 577044274189**Result** ✓ Passed

- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2013-06-21 10:34
MOT test number	497832673131
Result	✓ Passed
Notice	Front brake discs pitted on inner edge
Notice	Nail in offside front tyre



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
3 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-01
Last registration	2024-02-28
Complete history	See info



Registration #1	2010-07-01	17 mi
Registration #2	2013-06-21	31.340 mi
Registration #3	2014-06-23	37.872 mi
Registration #4	2015-06-24	42.657 mi
Registration #5	2016-04-04	47.752 mi
Registration #6	2016-04-05	47.752 mi
Registration #7	2017-04-21	53.681 mi
Registration #8	2018-04-16	60.233 mi
Registration #9	2019-04-16	66.233 mi
Registration #10	2020-04-16	72.233 mi
Registration #11	2021-04-16	78.233 mi
Registration #12	2022-04-16	84.233 mi
Registration #13	2023-04-16	90.233 mi
Registration #14	2024-02-28	96.233 mi
Registration #15	2024-02-28	96.233 mi
Registration #16	2024-02-28	96.233 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1482 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBD 371792