



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 POWERPULSE R-DESIGN PRO AWD
Colour	Black
Year of manufacture	2016
Top speed	137 mph
0 - 60 mph	7.4 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	52.3 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-04-28
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	14
Total items failed	7

MOT #6	2023-04-14 13:53
MOT test number	123080863823
Result	✓ Passed
Next expiry date	2024-04-28

MOT #5	2023-04-14 13:53
MOT test number	465976029686
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #4	2022-04-29 08:50
MOT test number	110009902642
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Electronic parking brake defective but can be satisfactorily operated (1.1.6 (d))
Advice	Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Offside Rear Nail in tyre
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))

**MOT #3**

2022-04-26 07:49

MOT test number

724105747029

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Electronic parking brake defective but can be satisfactorily operated (1.1.6 (d))
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Upper Engine mounting damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))
- Advice** Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Fail** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Rear Nail in tyre
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

MOT #2

2020-10-27 19:49

MOT test number

821470835145

Result**✓ Passed****MOT #1**

2019-07-29 14:59

MOT test number

194062261717

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
28 April 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	28 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-07-08
Last registration	2023-04-14
Complete history	See info



Registration #1	2016-07-08	29 mi
Registration #2	2019-07-29	68.369 mi
Registration #3	2020-10-27	80.006 mi
Registration #4	2021-05-20	85.277 mi
Registration #5	2022-05-20	90.548 mi
Registration #6	2023-05-20	95.819 mi
Registration #7	2024-05-20	101.090 mi
Registration #8	2025-05-20	106.361 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2008 mm
Height	1776 mm
Length	4950 mm
Wheel base	2984 mm
Kerb weight	2009 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1801395