



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Silver
Year of manufacture	2005
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	190 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-09-09
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-04-23
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	35
Total items failed	4

MOT #17 2021-04-08 08:32

MOT test number 446043961780

Result ✓ Passed

Next expiry date 2022-04-23

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

Minor Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16 2020-04-02 08:32

MOT test number 168633234105

Result ✓ Passed

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #15** 2019-04-12 08:26**MOT test number** 125015105594**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14** 2018-04-24 09:43**MOT test number** 855719277919**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #13** 2017-05-31 13:31**MOT test number** 171287963206**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #12** 2016-05-18 11:13**MOT test number** 685577217950**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #11**

2015-05-06 13:28

MOT test number

288736625427

Result

✓ Passed

Advice

Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #10

2014-11-28 14:45

MOT test number

727352134330

Result

✓ Passed

Advice

Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Notice

Engine covers fitted obscuring some components in the engine bay

Notice

Under-trays fitted obscuring some underside components

Advice

Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)

MOT #9

2013-11-18 13:04

MOT test number

426712623364

Result

✓ Passed

Advice

Brake pipe slightly corroded (3.6.B.2c)

Advice

Offside Brake hose slightly deteriorated (3.6.B.4d)

MOT #8

2012-11-21 11:46

MOT test number

159786922357

Result

✓ Passed

Advice

Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Notice

Vehicle's internal headlight adjuster altered to recheck lights

Advice

Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #7** 2012-11-21 11:46**MOT test number** 325126722396**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2011-10-29 13:34**MOT test number** 406042301314**Result** ✓ Passed**MOT #5** 2010-11-27 12:19**MOT test number** 843671630307**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2009-08-18 16:28**MOT test number** 730340039258**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2009-08-17 15:22**MOT test number** 612239029282**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2008-08-18 14:58
MOT test number	821081238287
Result	✓ Passed

MOT #1	2008-08-18 12:26
MOT test number	872791838245
Result	✗ Failed
Fail	Offside front brake binding (3.7.B.1)
Notice	N/s/front brake has BORDER LINE BINDING



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-09-09
Last registration	2021-04-08
Complete history	See info



Registration #1	2005-09-09	8 mi
Registration #2	2008-08-18	50.468 mi
Registration #3	2008-08-18	50.468 mi
Registration #4	2009-08-17	59.490 mi
Registration #5	2009-08-18	59.501 mi
Registration #6	2010-11-27	75.718 mi
Registration #7	2011-10-29	93.166 mi
Registration #8	2012-11-21	103.200 mi
Registration #9	2013-11-18	107.769 mi
Registration #10	2014-05-20	111.377 mi
Registration #11	2014-05-20	111.377 mi
Registration #12	2014-05-20	111.377 mi
Registration #13	2014-05-20	111.377 mi
Registration #14	2014-05-20	111.377 mi
Registration #15	2014-05-20	111.377 mi
Registration #16	2014-05-20	111.377 mi
Registration #17	2014-05-20	111.377 mi
Registration #18	2014-05-20	111.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1490 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1CD0491619