



report date: 2024-03-29

General information

Make	VOLVO
Model	S90 D4 MOMENTUM
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	400 Nm at 2.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	C






Internet history

Entry 2

Date	2022-08-26
Pictures	9
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2022-02-11
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-10-10
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #6	2023-10-11 08:09
MOT test number	351605521893
Result	✓ Passed
Next expiry date	2024-10-10
Advice	Engine covers and undertrays fitted obscuring components

MOT #5	2023-10-10 16:04
MOT test number	167069573329
Result	✗ Failed
Advice	Engine covers and undertrays fitted obscuring components
Fail	Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure 255/35/20 (5.2.3 (d) (ii))

MOT #4	2023-04-20 08:02
MOT test number	506203355689
Result	✓ Passed
Advice	Engine covers and undertrays fitted obscuring components

**MOT #3** 2022-10-25 13:06**MOT test number** 893507168597**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front tyre wearing inner edge**Advice** Engine covers and undertrays fitted obscuring components**MOT #2** 2022-09-14 12:04**MOT test number** 134811040352**Result** ✓ Passed**MOT #1** 2021-10-12 08:34**MOT test number** 565199710272**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords side-wall. (5.2.3 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
10 October 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	10 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 255,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>AE68FRK</b>
Plate since	2019-03-29
Current registration	<b>AE68FRK</b>
Plate since	2019-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-09-27
Last registration	2023-10-11
Complete history	<a href="#">See info</a>



Registration #1	2018-09-27	11 mi
Registration #2	2021-10-12	21.870 mi
Registration #3	2020-09-27	20.277 mi
Registration #4	2020-09-27	20.277 mi
Registration #5	2022-09-14	33.727 mi
Registration #6	2020-09-27	20.277 mi
Registration #7	2020-09-27	20.277 mi
Registration #8	2020-09-27	20.277 mi
Registration #9	2020-09-27	20.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2019 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1680 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	2224964
---------------	---------