



General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Grey
Year of manufacture	2010
Top speed	114 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 3

Date 2021-12-10

Pictures 4

Listing price [View report](#)



source: yesauto.com

Entry 2

Date 2021-12-07

Pictures 5

Listing price [View report](#)



source: autotrader.co.uk

Entry 1

Date 2021-02-06

Pictures 1

Listing price [View report](#)



source: autoonline.co.uk

**MOT history**

MOT expiry date	2025-04-08
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	25
Total items failed	1

MOT #15	2024-04-09 11:47
MOT test number	110370403573
Result	✓ Passed
Next expiry date	2025-04-08

MOT #14	2023-08-24 13:37
MOT test number	821530174029
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-12-01 16:06
MOT test number	727112698490
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement console (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2022-12-01 11:28

MOT test number

639562858215

Result**✗ Failed**

- MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement console (5.3.4 (a) (i))

MOT #11

2021-12-08 16:56

MOT test number

408455087575

Result**✓ Passed****MOT #10**

2021-06-09 10:24

MOT test number

213359434563

Result**✓ Passed****MOT #9**

2019-12-06 10:55

MOT test number

334063717163

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-11-27 12:04**MOT test number** 299705284754**Result** ✓ Passed**MOT #7** 2017-12-21 12:59**MOT test number** 253884921835**Result** ✓ Passed**MOT #6** 2017-02-27 14:59**MOT test number** 147423758672**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit @3mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit @3mm (4.1.E.1)**MOT #5** 2016-02-29 14:37**MOT test number** 446182683879**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush detaching (2.4.G.2)**Advice** Passenger air bag turned off**MOT #4** 2015-03-02 12:55**MOT test number** 109681965025**Result** ✓ Passed**MOT #3** 2014-03-11 09:40**MOT test number** 867030474061**Result** ✓ Passed**Notice** All four tyres are very slightly perishing.



MOT #2 2014-03-07 12:01

MOT test number 308176964095

Result ✗ Failed

Notice All four tyres are very slightly perishing.

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1 2013-02-13 10:20

MOT test number 576974543084

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
8 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-01
Last registration	2024-04-09
Complete history	See info



Registration #1	2010-03-01	14 mi
Registration #2	2013-02-13	20.192 mi
Registration #3	2014-03-07	24.064 mi
Registration #4	2014-03-11	24.064 mi
Registration #5	2015-03-02	29.833 mi
Registration #6	2016-02-29	40.181 mi
Registration #7	2017-02-27	51.006 mi
Registration #8	2017-12-21	57.395 mi
Registration #9	2018-11-27	65.710 mi
Registration #10	2019-12-06	75.631 mi
Registration #11	2020-05-20	85.552 mi
Registration #12	2020-05-20	85.552 mi
Registration #13	2020-05-20	85.552 mi
Registration #14	2020-05-20	85.552 mi
Registration #15	2020-05-20	85.552 mi
Registration #16	2020-05-20	85.552 mi
Registration #17	2020-05-20	85.552 mi
Registration #18	2020-05-20	85.552 mi
Registration #19	2020-05-20	85.552 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1592 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1399 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAY 215296