



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D4 R-DESIGN LUX NAV
Colour	Gold
Year of manufacture	2015
Top speed	143 mph
0 - 60 mph	6.8 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-09-22
Pictures	0
Listing price	<a href="#">View report</a>

source: [heycar.co.uk](#)

Entry 1

Date	2021-09-22
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-10-15
<b>MOT pass rate</b>	100 %
<b>MOT passed</b>	6
<b>Failed MOT tests</b>	0
<b>Total advice items</b>	10
<b>Total items failed</b>	0

<b>MOT #6</b>	2023-10-10 08:22
<b>MOT test number</b>	254857396753
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-10-15
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

<b>MOT #5</b>	2022-09-26 11:40
<b>MOT test number</b>	565298564778
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2021-09-27 08:55
<b>MOT test number</b>	998500201057
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

<b>MOT #3</b>	2020-09-30 10:30
<b>MOT test number</b>	465138086465
<b>Result</b>	✓ Passed



MOT #2	2019-10-11 10:41
MOT test number	155458987718
Result	✓ Passed

MOT #1	2018-10-16 09:05
MOT test number	116576772994
Result	✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
15 October 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	15 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>YY15RYA</b>
Plate since	2015-09-29
Current registration	<b>YY15RYA</b>
Plate since	2015-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-07-15
Last registration	2023-10-10
Complete history	<a href="#">See info</a>



Registration #1	2015-07-15	27 mi
Registration #2	2018-10-16	48.695 mi
Registration #3	2019-10-11	58.335 mi
Registration #4	2020-09-30	64.865 mi
Registration #5	2023-10-10	64.865 mi
Registration #6	2023-10-10	64.865 mi
Registration #7	2023-10-10	64.865 mi
Registration #8	2023-10-10	64.865 mi
Registration #9	2023-10-10	64.865 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1530 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1182027