





report date: 2024-03-29

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC3
Colour	Grey
Year of manufacture	2013
Top speed	109 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	420 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	39.8 mpg
Consumption combined	34.9 mpg
CO2 emission	213 g/km
CO2 label	K



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-07-29

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-09-14
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #10	2023-09-12 11:02
MOT test number	850094680426
Result	✓ Passed
Next expiry date	2024-09-14

MOT #9	2022-09-15 12:19
MOT test number	773403285205
Result	✓ Passed

MOT #8	2022-08-02 14:59
--------	------------------

MOT test number 352865735855

Result X Failed

Advice Nsr braking/suspension components appear to be covered in oily subsance

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. slight imbalance on application (1.2.1 (b) (i))

Fail Rear Brakes imbalanced across an axle nsr slower to achieve application (1.2.1 (b) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2021-07-27 12:24

MOT test number 139832355353

MOT #6 2020-07-31 10:31

MOT test number 354569704258

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Service brake fluctuating, but not excessively both (1.2.1 (e))

MOT #5 2020-07-31 10:31

MOT test number 533537387606

Result X Failed

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Rear Service brake fluctuating, but not excessively both (1.2.1 (e))

MOT #4 2019-06-07 09:38

MOT test number 288343795382

Result

Passed

MOT #3 2018-06-06 09:44

MOT test number 600372277358

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice (2.4.G.2)

Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice (2.4.G.2)

Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

MOT #1	2016-02-24 15:02
MOT test number	314180070444
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 14 September 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	history
O WILCI	,

· ·		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		TA
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-04-19
Last registration	2023-09-12
Complete history	See info



2013-04-19	21 mi
2016-02-24	22.377 mi
2017-06-07	31.404 mi
2018-06-06	43.084 mi
2019-06-07	55.250 mi
2020-07-31	63.172 mi
	11.777 es
	2016-02-24 2017-06-07 2018-06-06 2019-06-07

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1890 mm
Length	4760 mm
Wheel base	2790 mm
Kerb weight	2355 kg
Max. allowed weight	2990 kg

Additional information

Fuel tank capacity	87 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	e 12/12

Number of axles 2

Engine number 1KD2292612