



report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 115
Colour	Grey
Year of manufacture	2010
Top speed	116 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	280 Nm at 1.900 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	143 g/km
CO2 label	F





MOT history

MOT expiry date	2023-10-06
-----------------	------------

MOT pass rate	77 %
---------------	------

MOT passed	10
------------	----

Failed MOT tests	3
------------------	---

Total advice items	17
--------------------	----

Total items failed	12
--------------------	----

MOT #13	2022-09-13 14:55
---------	------------------

MOT test number	562147685954
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-10-06
------------------	------------

Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	---

Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
--------	--

Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	--

MOT #12	2021-09-30 17:14
---------	------------------

MOT test number	426822920382
-----------------	--------------

Result	✓ Passed
--------	----------

Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
-------	---

MOT #11	2020-10-07 09:27
---------	------------------

MOT test number	841790785764
-----------------	--------------

Result	✓ Passed
--------	----------

Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	--

**MOT #10**

2020-09-29 09:26

MOT test number

624488658522

Result**✗ Failed**

- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure Worn very un even , several cuts ,edges in tread . (5.2.3 (d) (ii))
- Fail** Nearside Front Headlamp insecure (4.1.1 (c))
- Fail** Brake servo defective or ineffective Pedal hard on BRT . (1.1.10 (a) (i))
- Fail** Nearside Front Macpherson strut likely to fail Leaking excessively . (5.3.3 (b) (ii))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))

MOT #9

2019-03-14 11:18

MOT test number

843291023161

Result**✓ Passed****MOT #8**

2019-03-13 10:52

MOT test number

905124882807

Result**✗ Failed**

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #7** 2018-04-24 12:47**MOT test number** 884780094992**Result** ✓ Passed**Advice** Windscreen has damage but does not materially affect drivers view**Advice** Items removed from driver's view prior to test**Advice** Rear Tyres heavily worn on Inner edges**MOT #6** 2017-04-12 15:25**MOT test number** 554727481223**Result** ✓ Passed**Advice** Offside Rear Tyre inner edge worn.**MOT #5** 2016-06-28 09:53**MOT test number** 903624537469**Result** ✓ Passed**MOT #4** 2015-07-01 09:06**MOT test number** 335622685132**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #3** 2014-07-03 09:55**MOT test number** 445024284191**Result** ✓ Passed**Notice** Front tyres wearing on edges**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #2	2014-07-03 09:55
MOT test number	589104284140
Result	✗ Failed
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Nearside Front Steering rack gaiter insecure (2.2.D.2d)
Notice	Front tyres wearing on edges
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2013-07-22 16:10
MOT test number	977493603224
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2024

X

MOT

Expired:
6 October 2023

Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	6 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-07-21
Last registration	2022-09-13
Complete history	See info



Registration #1	2010-07-21	7 mi
Registration #2	2013-07-22	17.503 mi
Registration #3	2014-07-03	23.812 mi
Registration #4	2015-07-01	29.659 mi
Registration #5	2016-06-28	35.863 mi
Registration #6	2017-04-12	41.275 mi
Registration #7	2018-04-24	75.810 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2020-05-20	115.277 mi
Registration #10	2021-05-20	135.277 mi
Registration #11	2022-05-20	155.277 mi
Registration #12	2023-05-20	175.277 mi
Registration #13	2024-05-20	195.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1491 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AU08714