



report date: 2024-03-29

## General information

Make	VOLKSWAGEN
Model	SCIROCCO TDI BLUEMOTION TECHNOLOGY
Colour	Black
Year of manufacture	2013
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-27
Pictures	3
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-21
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	20
Total items failed	3

MOT #11	2023-08-22 15:17
MOT test number	972437283636
Result	✓ Passed
Next expiry date	2024-08-21
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #10	2023-08-22 13:54
MOT test number	829324757560
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #9** 2022-08-22 14:11**MOT test number** 343444785442**Result** ✓ Passed

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Inner Tyre slightly damaged Wearing unevenly which may cause road noise or vibration (5.2.3 (d) (ii))
- Advice** Nearside Front Inner Tyre slightly damaged Wearing unevenly which may cause road noise or vibration (5.2.3 (d) (ii))

**MOT #8** 2022-08-22 14:11**MOT test number** 655708810934**Result** ✗ Failed

- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Inner Tyre slightly damaged Wearing unevenly which may cause road noise or vibration (5.2.3 (d) (ii))
- Pass with rectification** Front Undertray insecure (8.1.1 (b) (i))
- Advice** Nearside Front Inner Tyre slightly damaged Wearing unevenly which may cause road noise or vibration (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #7** 2021-08-06 16:50**MOT test number** 443861103756**Result** ✓ Passed**MOT #6** 2021-03-26 12:45**MOT test number** 577602460764**Result** ✓ Passed

- Advice** Undertray not fully secure (8.1.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both sides front (1.1.14 (a) (ii))

**MOT #5** 2020-03-07 09:25**MOT test number** 871779585335**Result** ✓ Passed**Advice** Engine cover and undertrays fitted**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Both rear tyres wearing uneven on inside edges**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-03-09 09:09**MOT test number** 776743780418**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #3** 2018-03-31 10:53**MOT test number** 568838942487**Result** ✓ Passed**MOT #2** 2017-10-20 14:36**MOT test number** 105084854300**Result** ✓ Passed**MOT #1** 2016-11-19 09:42**MOT test number** 541586542682**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
21 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	21 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-12-01
Last registration	2023-08-22
Complete history	<a href="#">See info</a>



Registration #1	2013-12-01	14 mi
Registration #2	2016-11-19	64.789 mi
Registration #3	2017-10-20	84.243 mi
Registration #4	2018-03-31	88.893 mi
Registration #5	2019-03-09	97.028 mi
Registration #6	2020-03-07	104.676 mi
Registration #7	2021-03-26	107.535 mi
Registration #8	2022-03-22	111.277 mi
Registration #9	2022-03-22	111.277 mi
Registration #10	2022-03-22	111.277 mi
Registration #11	2022-03-22	111.277 mi
Registration #12	2022-03-22	111.277 mi
Registration #13	2023-08-22	111.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CFHC520511