





General information

| Make | NISSAN |
|---------------------|----------------|
| Model | 350 Z V6 |
| Colour | Blue |
| Year of manufacture | 2008 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 296 BHP |
|-------------------------|---------------------|
| Max. torque | 358 Nm at 4.800 rpm |
| Engine capacity | 3.498 сс |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 16.8 mpg |
| Consumption extra urban | 32.1 mpg |
| Consumption combined | 24.1 mpg |
| CO2 emission | 280 g/km |
| CO2 label | Μ |







Internet history

| Entry | 1 |
|-------|---|
| | |

Date

2021-07-27

Pictures

9

Listing price

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-09-19 |
|--------------------|------------|
| MOT pass rate | 76 % |
| MOT passed | 13 |
| Failed MOT tests | 4 |
| Total advice items | 21 |
| Total items failed | 3 |

| MOT #17 | 2023-09-02 10:07 |
|---|------------------------|
| MOT test number | 473396026552 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-19 |
| Advice Nearside Rear Tyre worn close to legal limit/wo | rn on edge (5.2.3 (e)) |
| Advice Offside Rear Tyre worn close to legal limit/worn | on edge (5.2.3 (e)) |

| MOT #16 | 2022-09-05 12:07 |
|-----------------|------------------|
| MOT test number | 378321626624 |
| Result | ✓ Passed |

| MOT #15 | 20 | 21-09-14 10:49 |
|----------|--|----------------|
| MOT test | number | 229972494396 |
| Result | | ✓ Passed |
| Advice | Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) | |
| Advice | Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) | |





| MOT #14 | | 2021-09-08 12:52 |
|----------|--|------------------|
| MOT test | number | 272991052944 |
| Result | | 🗙 Failed |
| MAJOR | Emissions not tested due to exhaust condition (8.2.1.2 (d)) | |
| Advice | Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (| c)) |
| MAJOR | Exhaust has a major leak of exhaust gases back box (6.1.2 (a)) | |
| Advice | Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 | (c)) |
| | | |

| MOT #13 | | 2020-09-16 11:22 |
|------------|---|------------------|
| MOT test i | number | 504659118434 |
| Result | | ✓ Passed |
| Advice | Exhaust deteriorating. | |
| Advice | Front brake discs corroded on inner faces | |
| Advice | Exhaust has a minor leak of exhaust gases (6.1.2 (a)) | |

| MOT #12 | 2019-09-20 07:28 |
|-----------------|------------------|
| MOT test number | 467805135999 |
| Result | ✓ Passed |

| MOT #11 | 2019-09-06 08:52 |
|---|------------------|
| MOT test number | 917276842998 |
| Result | 🗙 Failed |
| DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Little reserve travel on park brake requires service or repair | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e)) | |





| MOT #10 | 2018-09-04 10:29 |
|--|------------------|
| MOT test number | 322951038465 |
| Result | ✓ Passed |
| Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a)) | |
| Advice Rear tyres worn close to wear indicator bars. | |
| MOT #9 | 2017 00 07 14:13 |

| МОТ #9 | 2017-09-07 14:13 |
|-----------------|------------------|
| MOT test number | 950208003120 |
| Result | ✓ Passed |

| МОТ #8 | 2017-08-29 07:19 |
|---|------------------|
| MOT test number | 900095451171 |
| Result | 🗙 Failed |
| Fail Offside Front Suspension arm rubber bush bonding deteriorated resulting in (2.4.G.2) | |

Fail Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

| MOT #7 | 2016-09-13 12:29 |
|-----------------|------------------|
| MOT test number | 821458269203 |
| Result | ✓ Passed |
| | |

| МОТ #6 | 2015-07-02 16:26 |
|-----------------|------------------|
| MOT test number | 246993085473 |
| Result | ✓ Passed |
| | |

| MOT #5 | 2014-06-30 12:57 |
|-----------------|------------------|
| MOT test number | 835821484164 |
| Result | ✓ Passed |





| MOT #4 | 2013-03-27 13:42 |
|---|------------------|
| MOT test number | 235396883005 |
| Result | ✓ Passed |
| AdviceWindscreen has damage to an area less than a 10mm circle within zoneAdviceRear Brake pad(s) wearing thin (3.5.1g) | e'A' (8.3.1a) |

| MOT #3 | 2012-03-02 13:16 |
|-----------------|------------------|
| MOT test number | 137582762485 |
| Result | ✓ Passed |

| MOT #2 | 2012-03-01 10:15 |
|--|------------------|
| MOT test number | 637301462066 |
| Result | 🗙 Failed |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |

| MOT #1 | | 2011-03-01 12:45 |
|----------|--|------------------|
| MOT test | number | 487130761061 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |



Tax & MOT check

| ✓ | ✓ |
|------------------|--------------------------------------|
| Taxed | MOT |
| Tax due: | Expires: |
| 1 March 2025 | 19 September 2024 |
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 19 September 2024 See MOT history |
| Full MOT history | See MOT histor |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | Μ |
| Single payment (12 months) | £ 695,00,- |
| Single six month payment | £ 382,25,- |
| Total payable by 12 monthly instalments | £ 729,75,- |





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---------|-------|
| Date | | |
| Category | | Lamp |
| Туре | | |
| Damage 2 | | AMPL |
| Date | | · · · |
| Category | 1000000 | AMPL |
| Туре | | |

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ana | |
|---|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 19 |
| First mileage registration | 2008-03-01 |
| Last registration | 2023-09-02 |
| Complete history | <u>See info</u> |



| Registration #1 | 2008-03-01 | 22 mi |
|--------------------------------------|------------|------------|
| Registration #2 | 2011-03-01 | 17.037 mi |
| Registration #3 | 2012-03-01 | 23.194 mi |
| Registration #4 | 2012-03-02 | 23.216 mi |
| Registration #5 | 2013-03-27 | 28.952 mi |
| Registration #6 | 2014-06-30 | 35.732 mi |
| Registration #7 | 2015-07-02 | 39.330 mi |
| Registration #8 | 2016-09-13 | 43.450 mi |
| Registration #9 | 2017-08-29 | 46.198 mi |
| Registration #10 | 2017-09-07 | 46.217 mi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | |
| | | 11.717 au |
| Registration #15 | | 11,777 au |
| - | | 01,000 est |
| Registration #15 | | 0.000 es |
| Registration #15 Registration #16 | | 0.000 es |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| S0501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Dimensions & weight

| Width | 1815 mm |
|------------------------|---------|
| Height | 1320 mm |
| Length | 4310 mm |
| Wheel base | 2650 mm |
| Kerb weight | 1542 kg |
| Max. allowed weight | 1820 kg |
| Additional information | |
| Fuel tank capacity | 80 |

| . , | |
|-----------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 2 |
| Engine number | 607467 |