



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D5 SE S40
Colour	Grey
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-09-24
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-21
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	17
Total items failed	7

MOT #19	2023-09-20 13:07
MOT test number	449983297441
Result	✓ Passed
Next expiry date	2024-09-21

MOT #18	2022-09-21 16:26
MOT test number	221520392239
Result	✓ Passed

MOT #17	2021-09-14 08:04
MOT test number	951314326415
Result	✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking in sidewall (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2021-09-14 08:04
MOT test number	196672914630
Result	✗ Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking in sidewall (5.2.3 (d) (ii))

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2020-09-09 13:09**MOT test number** 679956557748**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #14** 2020-09-09 07:52**MOT test number** 288267563131**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2019-09-12 10:48**MOT test number** 241545439449**Result** ✓ Passed**MOT #12** 2018-09-04 14:04**MOT test number** 916967488525**Result** ✓ Passed

**MOT #11** 2018-09-04 08:07**MOT test number** 124099552805**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2017-09-13 09:05**MOT test number** 568174691191**Result** ✓ Passed**MOT #9** 2016-09-22 15:54**MOT test number** 934524631612**Result** ✓ Passed**MOT #8** 2015-10-21 11:29**MOT test number** 257985334640**Result** ✓ Passed**Advice** Undertrays fitted obscuring some underside vehicle components**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2015-10-21 11:28**MOT test number** 750544425820**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Undertrays fitted obscuring some underside vehicle components**Pass with rectification** Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)

**MOT #6** 2014-10-29 11:37**MOT test number** 117582704331**Result** ✓ Passed**Notice** Drivers side front lower wishbone, rear bush leaking oil**MOT #5** 2013-10-08 14:54**MOT test number** 758001983281**Result** ✓ Passed**MOT #4** 2012-10-10 12:54**MOT test number** 158604582269**Result** ✓ Passed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Nearside front wiper smearing slightly**MOT #3** 2011-10-13 16:24**MOT test number** 349266381417**Result** ✓ Passed**MOT #2** 2010-10-12 16:44**MOT test number** 971635680269**Result** ✓ Passed**MOT #1** 2010-10-12 16:44**MOT test number** 194645780259**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
21 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-10-31
Last registration	2023-09-20
Complete history	See info



Registration #1	2007-10-31	17 mi
Registration #2	2010-10-12	18.615 mi
Registration #3	2011-10-13	24.553 mi
Registration #4	2012-10-10	29.444 mi
Registration #5	2013-10-08	34.273 mi
Registration #6	2014-10-29	39.283 mi
Registration #7	2015-10-21	43.030 mi
Registration #8	2015-10-21	43.030 mi
Registration #9	2016-09-22	45.754 mi
Registration #10	2017-09-13	48.843 mi
Registration #11	2018-09-20	51.932 mi
Registration #12	2019-09-20	55.021 mi
Registration #13	2020-09-20	58.110 mi
Registration #14	2021-09-20	61.199 mi
Registration #15	2022-09-20	64.288 mi
Registration #16	2023-09-20	67.377 mi
Registration #17	2023-09-20	67.377 mi
Registration #18	2023-09-20	67.377 mi
Registration #19	2023-09-20	67.377 mi
Registration #20	2023-09-20	67.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1543 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	516960
---------------	--------